

ASS. REC. BY:

REF: 1CS/ 2200 7304/KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 8127K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNE 28102Yr Regn: 03, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: RenaultScenicc.c. 1461Colour: M. Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 53431

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIC/ RFA 000 63211981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: Davanti195/55R20Continental

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 6 mmL/Bal. 7 mmL/Bal. 6 mmD.O.A. 29/7/22D.O.I. 2/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassals frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Data/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Data/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐

: Site Insp (\$ _____)

Transportation: _____

S - RS. \$ _____

☐ : Interview (\$ _____)

: Photos _____

☐ : Tech Invs (\$ _____)

: Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

EngNo: _____

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)60 Jalan Lam Huat, #07-43
Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

Kenneth

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	29/07/2022
Vehicle Reg. No.:	SNE2810Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Vehicle Reg. Date:	01/03/2022
Vehicle Colour:	RED		
Engine No:	K9KF649D060176	Chassis No:	VF1RFA00063211961
Odometer:	53431 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

*5 days**Not within
Mercury Bepain*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount

21,148.73

87.00

2,830.00

0.00

0.00

Calculated Gross Total (S\$) 24,065.73**- Excess (S\$)** 2,000.00**(S\$)** 22,065.73**+ GST 7.00% (S\$)** 1,544.60**Nett Amount (S\$)** 23,610.33**COST OF CLAIMS**

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

This claim is handled by: **TAN CHIN CHIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2022)
 Parts: M1-MPV RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

			%Disc	%Depr	Amount	
1	1	*651004703R FRONT BONNET	RM 0.00	0.00	*1,509.76 F	✓
2	1	*656016673R BONNET LOCK	DIY 0.00	0.00	*208.32 F	✓
3	1	*654000247R FRONT BONNET HINGE RH	DIY 0.00	0.00	*150.41 F	✓
4	1	*654013594R FRONT BONNET HINGE LH	DIY 0.00	0.00	*150.41 F	✓
5	1	*658408772R FRONT BONNET INSULATOR	RM 0.00	0.00	*330.62 F	X
6	1	*654704597R FRONT BONNET DAMPER LH	RM 0.00	0.00	*125.66 F	X
7	1	*654704597R FRONT BONNET DAMPER RH	RM 0.00	0.00	*125.66 F	X
8	1	*260101271R FRONT HEADLAMP RH	my CM 0.00	0.00	*999.60 F	✓
9	1	*260602165R FRONT HEADLAMP LH	✓ 0.00	0.00	*999.60 F	✓
10	1	*622907255R FRONT CENTRE BRACE BRACKET	0.00	0.00	*148.84 F	?
11	1	*620223972R FRONT BUMPER	CM 0.00	0.00	*1,877.34 F	✓
12	1	*625005785R FRONT SUPPORT PANEL	0.00	0.00	*1,360.00 F	✓
13	4	*253A49995R FRONT PARKING SENSOR	0.00	0.00	*2,496.24 F	?
14	2	*2843896148R FRONT BLIND SPOT SENSOR RH	RM 0.00	0.00	*810.20 F	X
15	1	*623821034R FRONT RADIATOR GRILLE BLACK	CM 0.00	0.00	*296.80 F	✓
16	1	*623855072R FRONT RADIATOR GRILLE MOULDING (CHROME)	CM 0.00	0.00	*261.80 F	✓
17	1	*622561964R FRONT RADIATOR GRILLE	CRM 0.00	0.00	*530.60 F	✓
18	1	*628905855R FRONT GRILLE EMBLEM	CM 0.00	0.00	*187.04 F	✓
19	1	*620363937R FRONT RADIATOR TOP GARNISH	CM 0.00	0.00	*513.40 F	✓
20	1	*752106346R FRONT BUMPER REINFORCEMENT	0.00	0.00	*833.72 F	?
21	1	*620901789R FRONT BUMPER LOWER REINFORCEMENT GARNIS	0.00	0.00	*267.79 F	?
22	1	*7711428130 COOLANT 5L	0.00	0.00	*27.10 F	?
23	1	*921004063R AIRCON CONDENSER	0.00	0.00	*1,041.60 F	?
24	1	*144614EA1B ENGINE INNER COOLER	0.00	0.00	*1,005.87 F	?
25	1	*214105169R RADIATOR	0.00	0.00	*812.44 F	?
26	1	*214819674R RADIATOR FAN COWLING ASSY	0.00	0.00	*1,049.66 F	?
27	1	*628109433R RADIATOR GRILLE INNER AIR DUCT	0.00	0.00	*185.13 F	?
28	1	*215595656R RADIATOR INNER AIR DUCT	0.00	0.00	*115.13 F	?
29	1	*215586371R INTERCOOLER AIR DUCT	0.00	0.00	*52.19 F	?
30	1	*214F62853R FRONT LOWER AIR INTAKE FLAP GUIDE	0.00	0.00	*669.08 F	?
31	1	*656220664 front bonnet lock handle	my CM 0.00	0.00	*84.11 F	✓

F=Franchise part.

Sub Total (\$\$) 19,226.12
 + Margin on L,N Items 10.00% (\$\$) 1,922.61
 Total Parts (\$\$) 21,148.73

Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	6	FRONT BUMPER SCREW	42.00 ✓
2	1	FRONT NUMBER PLATE	45.00 X
Sub Total (S\$)			87.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPLACE / WELADING REALIGN FROT BUMPER , BONNET, FRONT WINDS SUB FRAME, CHASSISD MEMBER FRONT ASSY LH/RH AND ALL NECESSARY ETC	New	1,200.00 500
2	TO REMOVE & REPLACE RADIATOR FAN , HOSE AND AIR COND CONDENSER HOSE , FAN INLUDING VECUUM AND TOP UP GAS	New	250.00 7
3	TO DIAGNOSTIC SETTING PASSENGER & DRIVER RESTRAINT SYSTEM AND RESETTNG OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00 7
4	TO RESPRAY FRONT ACCIDENT PORTION, BONNET,FENDER LH & RH, BUMPER CHASSIS MEMBERASSY RH/LH AND NECESSARY ETC	New	1,000.00 600
Gross Labour Cost (S\$)			2,830.00

Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/08/2022 09:45 (SGT)
Reported by	Driver
Date of Accident	29/07/2022 17:49 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	MCNAIR ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNE2810Z
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Scenic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1499

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MCF22A00000100

DRIVER

Name of Driver	ONG LAI THIAM
NRIC No	SXXXXX039H

MC NAIR ROAD

A B

VEH A - SNE 2810 Z

VEH B - GBB 3586 Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29-07-2022, time 17:49:24 at McNair Road. I couldn't brake in time and rear-ended vehicle GBB 3586 Y

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Driver's Signature
(if not the policyholder)

Reporting Centre Personnel's Signature
Name:

