



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22007306/Kvcm4	
			Date: 26/08/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3329J	Veh. Inspected	SJJ 5708M	
Policy No.	D-22099187MFBP	Coverage (\$)	0.00	
Claim No.	D22002336MFBP	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	01/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI SWIFT (M)	c.c	1328	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ZC11S402427	Colour	BLACK	
Odometer	205937 KM	Steering	JAMMED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	MICHELIN	8 mm	
L/H Front Tyre	195/55 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/07/2022	Inspection Date	02/08/2022	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	