

KFS motor

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

INVOICE NO : TEST
DATE : 29-08-2022

VEHICLE NO. : SLD7929L
ACCIDENT DATE : 29-07-2022 10:00
THIRD PARTY REF. : SDT2678D

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SLD7929L HONDA VEZEL

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	REAR BOOT COVER	530.00
1	REAR BUMPER	170.00
1	REAR BUMPER SIDE RH	65.00
1	REAR BUMPER REFLECTOR RH	35.00
1	REAR BUMPER SIDE RETAINER RH	12.00
10	REAR BUMPER CLIP@\$2.50	25.00
		<hr/>
		837.00
	ADD 20 %	167.40
	TOTAL (A)	<hr/>
		1,004.40

SPECIAL NETT ITEMS

1	REAR WINDSCREEN GUM	50.00
1	REAR REVERSE SENSOR	200.00
		<hr/>
	TOTAL (C)	250.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	120.00
1	TO REMOVE/REFIT REAR FENDER INNER GARNISH & ETC	60.00
1	TO REMOVE ALL NECESSARY AFEFCTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	600.00

VEHICLE NO. : SLD7929L
ACCIDENT DATE : 29-07-2022 10:00
THIRD PARTY REF. : SDT2678D

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	SPRAYPAINTING CHARGE	600.00
	TOTAL (D)	<u>1,410.00</u>
	TOTAL REPAIR COST :	<u>2,664.40</u>
	G S T % :	<u>186.50</u>
	INVOICE AMOUNT :	<u>2,850.90</u>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD
 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
 199555

DATE : 01-08-2022

VEHICLE NO. : SLD7929L
 ACCIDENT DATE : 29-07-2021 10:00
 THIRD PARTY REF. : SDT2678D

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SLD7929L HONDA VEZEL

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER	590.00 <i>BA 530</i>
2	1	REAR BOOT WINDSCREEN RUBBER	60.00 <i>per</i>
3	1	REAR BOOT LOCK	55.00 <i>?</i>
4	1	REAR BOOT RUBBER	0.00 <i>stuck</i>
5	1	REAR BUMPER	160.00 <i>del 170</i>
6	1	REAR BUMPER SIDE RH	75.00 <i>del 65</i>
7	1	REAR BUMPER REFLECTOR RH	45.00 <i>over 35</i>
8	1	REAR BUMPER SIDE RETAINER RH	10.00 <i>X 12</i>
9	10	REAR BUMPER CLIP@2.50	25.00 <i>new</i>
10	1	REAR END PANEL	275.00 <i>?</i>
11	1	REAR EXHAUST MUFFLER <i>dismantle plus 10.00</i>	360.00 <i>?</i>
			1,655.00
ADD 20 %			331.00
TOTAL (A)			<u>1,986.00</u>

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN GUM	50.00 <i>new</i>
2	1	REAR REVERSE SENSOR	300.00 <i>200.00</i>
TOTAL (C)			<u>350.00</u>

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 <i>30.00</i>
---	---	------------------------	--------------------



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLD7929L
ACCIDENT DATE : 29-07-2011 10:00
THIRD PARTY REF. : SDT2678D

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	120.00 ✓
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH & ETC	100.00 60
4	1	TO REMOVE ALL NECESSARY AFEFCTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	820.00 600
5	1	SPRAYPAINTING CHAREGS	750.00 600
TOTAL (D)			1,840.00
ESTIMATE TOTAL			4,176.00

Tanfah 97495749
 WP' 22/8/22 R 1140
 tanfah @ 11 months
 5 days
 * Resunary before paint.