

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0640/2022/EQ
DATE : 1-Aug-22
WIP : 34995

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. DINESH KUMAR S/O TEVERMUTHU
ADDRESS : BLK 455A ANG MO KIO STREET 44
#31-03
SINGAPORE 561455
TELEPHONE : HP +65 97364753
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070165966-01
VEHICLE NO : **SMW 6617 G**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI S-TRONIC
MODEL YEAR : 30/11/2020
ENGINE NO : DEM 027075
CHASSIS NO : WAUZZZF53MA011396
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Jul-22
PLACE OF ACCIDENT : 36 MIMOSA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ (photo) 800.00	?
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00	/
5	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	/
6	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ (photo) 3,600.00	/
SUB-TOTAL LABOUR CHARGES		: \$ 7,960.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	✓
8	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
9	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	✓
10	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	✓
11	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	250
12	TO PLACE VEHICLE ON CAR O-LINER. <i>Cphm</i>	S/N \$	2,400.00	7
SUB-TOTAL LABOUR CHARGES		:	\$ 6,280.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
14	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00	?
15	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	?
16	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00	/
17	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS LHS SILL PANEL TRIM AND LHS FRONT DOOR. TO REPAIR RHS FRONT DOOR AND BOTH UPPER A-PILLARS. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR WITH LHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 14,400.00 10 x 5000	5000
18	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS, BOTH UPPER A-PILLARS, LHS A-PILLAR, LHS SILL PANEL, DOOR ENTRANCE, LHS SILL PANEL TRIM AND LHS FRONT FENDER TOP SUPPORT.	\$ 11,000.00 6.5 x 550	3575
SUB-TOTAL LABOUR CHARGES		: \$ 28,160.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6617 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
19	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00 /	
20	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 43,304.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	2,493.00	
2	FRONT BUMPER SECURING STRIP / nec	2	\$	79.00	
3	FRONT BUMPER GRILLE - CENTER / BR	1	\$	219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE / BR	1	\$	293.00	
5	FRONT BUMPER SPOILER / MIS	1	\$	599.00	
6	FRONT BUMPER AIR GUIDE - LH / RH / MIS	2	\$	144.00	
7	FRONT BUMPER CLOSING ELEMENT / ?	1	\$	293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH / MIS	2	\$	302.00	
9	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH / MIS	1	\$	108.00	
10	FRONT BUMPER TRIM - CENTER / MIS	1	\$	127.00	
11	RADIATOR GRILLE / BR	1	\$	1,881.00	
12	RADIATOR COVER CAP / ?	1	\$	141.00	
13	RADIATOR BRACKET / ?	1	\$	19.00	
14	RADIATOR SECURING PLATE / ?	1	\$	12.00	
15	FRONT PARKING AID SENSOR - INNER / OUTER / MIS	2	\$	530.00	
16	FRONT PARKING AID SENSOR ASSIST SYSTEM - SIDE / MIS	1	\$	265.00	
17	FRONT PARKING AID SEAL RING / APC	4	\$	10.00	
18	FRONT BUMPER WIRING SET / TA	1	\$	449.00	
19	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$	163.00	
20	FRONT BUMPER REINFORCEMENT BEAM / DN	1	\$	899.00	
SUB TOTAL SPARE PARTS		:	\$	9,026.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION - LH / RH / <i>BR</i>	<i>2</i> 1	\$ 82.00	
22	FRONT BUMPER BRACKET - LH / <i>BT</i>	1	\$ 254.00	
23	FRONT BUMPER TOP COVER / <i>CRU</i>	1	\$ 143.00	
24	CAUTION SIGN / <i>MC</i>	1	\$ 16.00	
25	AIR CONDITIONER STICKER / <i>MC</i>	1	\$ 9.00	
26	FRONT LOCK CARRIER BRACKET / <i>BT</i>	1	\$ 154.00	
27	FRONT BUMPER SUPPORT - LH / RH / <i>MC</i>	2	\$ 64.00	
28	POP RIVET / <i>MC</i>	4	\$ 4.00	
29	FRONT HORN HIGH TONE - LH / <i>BT BR</i>	1	\$ 134.00	
30	FRONT HORN BRACKET - LH / <i>BT</i>	1	\$ 33.00	
31	FRONT FENDER - LH / RH / <i>DO</i>	<i>2</i> 1	\$ 2,378.00	
32	FRONT FENDER ATTACHMENT PARTS / <i>MC</i>	1	\$ 55.00	
33	FRONT FENDER CLOSING ELEMENT - LH / <i>MC</i>	1	\$ 83.00	
34	FRONT FENDER BRACKET - LH / <i>BT</i>	1	\$ 41.00	
35	POP RIVET / <i>MC</i>	11	\$ 42.00	
36	FRONT FENDER BRACKET - LH / <i>BT</i>	1	\$ 65.00	
37	FRONT FENDER BRACKET - RH / <i>BT</i>	1	\$ 40.00	
38	FRONT FENDER BRACE - LH / <i>BT</i>	1	\$ 132.00	
39	FRONT FENDER BRACKET - LH / <i>BT</i>	1	\$ 55.00	
40	FRONT FENDER COVER - LH / <i>BR</i>	1	\$ 20.00	
SUB TOTAL SPARE PARTS		:	\$ 3,804.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

		DAMAGED PARTS & PRICES			REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
41	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$	37.00	
42	FRONT FENDER WHEEL HOUSING LINER - LH / TN	1	\$	299.00	
43	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS / NC	1	\$	176.00	
44	FRONT WHEEL HOUSING LINER - RH ?	1	\$	299.00	
45	FRONT WHEEL SPOILER - LH / RH - MIS	2	\$	164.00	
46	FRONT SPOILER - LH - MIS	1	\$	39.00	
47	FRONT STONE CHIP GUARD - LH - NC	1	\$	57.00	
48	FRONT BRACKET TRIM - LH ?	1	\$	27.00	
49	FRONT FENDER TRIM - LH / RH - BR	1	\$	342.00	
50	BONNET - DO	1	\$	3,491.00	
51	BONNET ATTACHMENT PARTS ?	1	\$	128.00	
52	FRONT LID HINGE - LH / RH ?	2	\$	932.00	
53	FRONT IMPACT PROTECTION - CENTER / LH / RH - NC	3	\$	93.00	
54	BONNET SOUND ABSORBER - CR4	1	\$	382.00	
55	FRONT FENDER COVER - LH - BR	1	\$	81.00	
56	FRONT FENDER COVER - BR	1	\$	40.00	
57	FRONT HEADLAMPS COVER - LH - BR	1	\$	49.00	
58	FRONT FENDER COVER - LH ?	1	\$	18.00	
59	BONNET ABSORBER ?	2	\$	256.00	
60	BONNET STRIKER - LH - BT	1	\$	56.00	
SUB TOTAL SPARE PARTS		:	\$	6,966.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

		DAMAGED PARTS & PRICES			REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
61	BONNET LOCK / BT	1	\$	228.00	
62	BONNET LOCK CABLE - RH ?	1	\$	82.00	
63	FRONT PLENUM CHAMBER COVER - RH / CVI	1	\$	108.00	
64	FRONT HEADLIGHT - LH / BR	1	\$	8,172.00	
65	HOSE / TN	1	\$	42.00	
66	FRONT COMPENSATING PIECE / MIS	3	\$	136.00	
67	FRONT LIFT CYLINDER BRACKET - LH / MIS	1	\$	17.00	
68	FRONT LIFT CYLINDER - LH / MIS	1	\$	217.00	
69	FRONT CORRUGATED PIPE / TN	1	\$	107.00	
70	COOLANT RADIATOR LOCK CARRIER MOUNTING / 00	1	\$	1,127.00	
71	FRONT COOLANT REGULATOR SUPPORT - LH ?	1	\$	43.00	
72	FLUID RESERVOIR AC CONDENSER ?	1		TBC	
73	A/C REFRIGERANT LINE ?	3	\$	844.00	
74	A/C REFRIGERANT PIPE / BT	1	\$	585.00	
75	FRONT A/C REFRIGERANT PIPE BRACKET / BR	2	\$	30.00	
76	CHARGE AIR COOLER / BT	1	\$	654.00	
77	PRESSURE PIPE ?	1	\$	496.00	
78	RADIATOR ?	1	\$	1,010.00	
79	FRONT READY-MIX COOLANT ? / PC	6	\$	282.00	
80	FRONT AIR GUIDE - LH / RH / UPPER / LOWER / BR 1.5		\$	118.00	
SUB TOTAL SPARE PARTS			\$	14,298.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	FRONT WINDSCREEN / <i>PR</i>	1	\$	1,625.00	
82	FRONT RAIN SENSOR GEL FOIL / <i>MC</i>	1	\$	130.00	
83	FRONT RETAINING SPRING X	1	\$	24.00	
84	FRONT CAMERA SILICONE PAD / <i>MC</i>	1	\$	123.00	
85	FRONT CAMERA PRIMER / <i>MC</i>	1	\$	22.00	
86	FRONT WATER DEFLECTOR STRIP - LH / RH X	2	\$	150.00	
87	FRONT DOOR - LH / <i>MC</i>	1	\$	3,977.00	
88	FRONT OUTER DOOR SEAL - LH / <i>MC</i>	1	\$	247.00	
89	BONDING AGENT / <i>MC</i>	1	\$	51.00	
90	CLEANING SOLUTION / <i>MC</i>	1	\$	74.00	
91	APPLICATOR / <i>MC</i>	1	\$	8.00	
92	FRONT DOOR CATCH - LH ?	1	\$	134.00	
93	FRONT DOOR TRIM - LH / RH / <i>PR</i>	12	\$	342.00	
94	FRONT TRIM STRIP WINDOW SLOT SEAL - LH / RH ?	12	\$	892.00	
95	ROOF MOLDING - LH / RH / <i>TA</i>	12	\$	1,412.00	
96	FRONT PILLAR A/B FRAME MEMBER - LH ?	1	\$	2,344.00	
97	FRONT SILL TRIM STRIP - LH / <i>PR</i> ?	1	\$	133.00	
98	FRONT SIDE MEMBER TRIM - LH / <i>CR4</i>	1	\$	916.00	
99	SECURING CLIPS ATTACHMENT PARTS / <i>MC</i>	1	\$	136.00	
100	ADHESIVE TAPES / <i>MC</i>	1	\$	221.00	
SUB TOTAL SPARE PARTS			:	\$	12,961.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
101	PICTOGRAM FOR AIRBAG / CHILD'S SEAT STICKER ¹	1	\$	27.00	
102	FRONT STEERING WHEEL AIRBAG ✓ ^{OR}	1	\$	4,092.00	
103	FRONT PASSENGER SIDE AIRBAG UNIT ✓ ^{OR}	1	\$	4,853.00	
104	FRONT HEAD AIRBAG UNIT - LH / RH ✓ ^{OR} ⁽²⁾	2	\$	4,138.00	
105	FRONT SPORTS STRNG WHEEL MULTIFUNCT ² ✓ ^{MT}	1	\$	2,641.00	
106	FRONT AIR DUCT DASHBOARD 2 ✓ ^{OR}	1	\$	5,901.00	
107	FRONT WINDSCREEN DEFROSTER NOZZLE - RH [?]	1	\$	185.00	
108	FRONT WINDSCREEN DEFROSTER NOZZLE - RH [?]	1	\$	137.00	
109	FRONT MOULDED HEADLINER ✓ ^{CR4}	1	\$	2,306.00	
110	FRONT A-PILLAR TRIM - LH / RH [?]	2	\$	458.00	
111	FRONT B-PILLAR TRIM - UPPER LH / RH [?]	2	\$	520.00	
112	FRONT D-PILLAR TRIM - LH / RH [?]	2	\$	470.00	
113	FRONT C-PILLAR TRIM - LH / RH [?]	2	\$	332.00	
114	FRONT & REAR FOLDING GRAB HANDLE - LH / RH [?]	4	\$	662.00	
115	FRONT THREE-POINT AUTOMATIC SEAT BELT - LH / RH [?] ⁽²⁾ ✓ ^{Ind}	2	\$	2,454.00	
116	FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH [?]	2	\$	383.00	
117	FRONT AIRBAG CONTROL UNIT ✓ ^m	1	\$	2,364.00	
118	FRONT AIRBAG CRASH SENSOR ✓ ^{nc}	3	\$	1,344.00	
119	FRONT CENTRAL PROTECTION ✓ ^{nl}	1	\$	590.00	
120	FRONT ALUMINIUM RIM (L4) ✓ ^{OR}	1	\$	1,889.00	
SUB TOTAL SPARE PARTS			\$	35,746.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	RUBBER VALVE / MC ?	1	\$	4.00	
122	FRONT ASSEMBLY CARRIER ?	1	\$	2,096.00	
123	FRONT CONSOLE - LH ?	1	\$	523.00	
124	FRONT GEARBOX SUPPORT ?	1	\$	90.00	
125	FRONT GEARBOX MOUNTING ?	1	\$	235.00	
126	FRONT WISHBONE LINK - LH ?	1	\$	605.00	
127	FRONT SUSPENSION GUIDE - LH ?	1	\$	1,057.00	
128	FRONT & REAR UPPER GUIDE - LH ?	2	\$	1,150.00	
129	FRONT WHEEL BEARING HOUSING - LH ?	1	\$	1,070.00	
130	FRONT SWIVEL JOINT - LH ?	1	\$	214.00	
131	FRONT WHEEL HUB - LH ?	1	\$	498.00	
132	FRONT FLANGE DOUBLE ANGLED BALL BEARING - LH ?	1	\$	273.00	
133	FRONT BEARING WHEELHUB - LH ?	1	\$	884.00	
134	FRONT SUSPENSION FORKS - LH ?	1	\$	293.00	
135	FRONT COUPLING ROD ?	2	\$	258.00	
136	FRONT ANTI-ROLL BAR MARKED GREEN ?	1	\$	478.00	
137	FRONT CONSTANT VELOCITY JOINTS DRIVE SHAFT ?	1	\$	2,999.00	
138	FRONT GAS SHOCK ABSORBER ?	1	\$	342.00	
139	FRONT STEERING RACK ?	1	\$	7,318.00	
140	FRONT TRACK ROD - LH ?	1	\$	109.00	
SUB TOTAL SPARE PARTS		:	\$	20,496.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6617 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	FRONT TIE ROD END - LH ?	1	\$	217.00
142	FRONT LOWER NOISE INSULATION ? - BR	1	\$	640.00
143	FRONT CONNECTING PLATE - LH ? ✓ DD	2	\$	520.00
144	FRONT FUSE HOLDER AND RELAY PLATE SUPPORT - LH ?	1	\$ - BR	53.00
145	FRONT UNDERBODY TRIM - LH ?	1	\$	51.00
146	FRONT NO PLATE ✓ ne	S/N	\$	60.00
147	ARCYLIC SEALANT ✓ ne	S/N	\$	180.00
148	CAVITY WAX - ne	S/N	\$	140.00
149	STONE CHIP ✓ ne	S/N	\$	180.00
150	METAL FILLER POWDER - ne	S/N	\$	280.00
151	FRONT WINDSCREEN SEALANT - ne	S/N	\$	200.00
152	LHS FRONT TYRE ✓ CRN	S/N	TBC	
153	SUNDRIES ?		\$	1,000.00
TOTAL SPARE PARTS		:	\$	106,818.00
TOTAL LABOUR CHARGES		:	\$	43,304.00
GRAND TOTAL		:	\$	150,122.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Star (LKK)
1/8/22, 4.7p

OP-M AL
EXcess?

P/P
5 PL y
20 dy 5

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT