

Your Ref : DMPC2200326H/CT

Date: 22nd Aug 2021

Our Ref : CS4/ICS22007322/Tvy3e2

M/s ECICS Ltd

10 Eunos Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMD 9920K
ACCIDENT ON 31/07/2022**

Instruction was received to inspect the vehicle Reg. No. SMD 9920K. The inspection was conducted on 02/08/2022 at the premises of M/s Yew Tee Automobile Tech PL, Blk 25 Kaki Bukit Road 4 #01-61 Synergy @ Kaki Bukit, Singapore 417800.

The following vehicle information was recorded:

Registration Number	: SMD 9920K
Make/Model	: Mercedes Benz C200 AMG A
Year of Registration	: 2017
Body Colour	: White
Chassis Number	: WDD2050422R171783
Engine Capacity	: 1991 cc

The vehicle caught fire. The cause of fire probably due to electrical. Wirings leading from Engine Control Module (ECM). (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 126,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 54,353.00)
Nett Liability	<u>S\$ 71,647.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.