

STATEMENT

PARTICULARS

Name : SONG JUN YANG, SIMON
 NRIC / Passport No. : S8518073H
 Address : BLK 571 HANGANG ST 51 #04-121 S(530571)
 Telephone : (R) _____ (O) _____
 (HP) 92261188
 Sex / Age : M / 37
 Occupation / Name of Company : SALES MANAGER / BRAKING POINT (S) PTE. LTD.
 Nationality : S'POREAN

Recorded By : MUHD NAZRI Date : 3/8/2022 Time: 1300 HRS
 Place Recorded: YEW TEE AUTOMOBILE
 Language Spoken: ENGLISH Interpreted By: N/A

FACTS OF CASE:

I am the owner and only driver of SMD 9920K which caught fire on 31/7/2022 at 1530 hours at Paterson Hill. I was from home. I had to deliver an item to a customer at Takashimaya Shopping Centre. I took the CTE (City) from Ang Mo Kio Ave 5 and exited at Orchard Road. My wife was with me. After delivering the item, I came out into Paterson Hill and was headed towards Turret Bank Road. I was going to Bukit Merah to make another delivery. I was travelling on the middle lane after the 10N Orchard junction. I suddenly smelt something burning and asked my wife about it. Then I saw white smoke coming from the top ~~part~~ center portion of the front bonnet. I then saw the engine check light and other warning lights on the dashboard. I did not notice ~~what~~ ~~error~~ if there were any error messages displayed as I was panicking. I wound down the windows and stopped the car to the side of the road and switched off the engine.

I took ~~exit~~ the car and took a video of the white smoke emitting from the front bonnet. The smoke became more intense ~~and~~. I quickly called 995 and went to the nearest condo to get help from the security at the Marg condo.

Signed:

Simon
3/8/2022

Recorded by:

MUHD NAZRI
N/A

3/8/2022



Auto
Consultants
Pte Ltd

STATEMENT

When I returned with a security guard and fire extinguisher, the car was already on fire. There was a grab rider trying to put out the fire with a small fire extinguisher. The security guard also tried to put out the fire. Within 2 minutes the police arrived followed by the SCDF. SCDF arrived about 15 minutes from the time I called 995. Firefighters opened the front bonnet and put out the fire with a water jet within 5 minutes.

I assisted the SCDF in their preliminary investigations. I asked the SCDF fire investigator what caused the fire. He told me it started from the engine compartment but he could not determine what caused it. I called my friend for advice when I saw the white smoke and he told me to call the ECICS authorized workshop. That's when I called Yew Tee Automobile. The tow truck had already arrived earlier but the driver was on standby until SCDF gave me permission to tow the car. The car was towed to Yew Tee Automobile. I managed to grab my customer's items from the car and my valuables. I took a grab and delivered the item with my wife before heading home.

I went to Yew Tee Automobile on 1/8/2022 at 1501 hours to make an insurance report. The police said a police report was unnecessary and already took down my statement.

I bought the car used in August 2020 from a private seller. I've been driving this car for about 2 years. No issues with the car except for the usual wear and tear. The last servicing done on 18 July 2022 RevZone performance. I have not added any aftermarket electrical or electronic components to the car. I only changed to aftermarket 18 inch rims after I bought the car as the rims were worn. I only added a carbon fibre rear spoiler and other exterior parts carbon fibre exterior parts.

I wish to state that I did not consume any alcohol or take any medication that could cause drowsiness and may impair my ability to drive at the time of the incident.

I wish to affirm that the above statement is correct and true at the time it was taken.

Signed:

3/8/2022

Recorded by:

MUTHU NARAYAN

3/8/2022