

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 03 Aug 2022

## **Preliminary Advice**

Vehicle No	: SMD9920K	Accident Date	: 31/07/2022
Make	: MERCEDES-BENZ C200	Policy No.	: MPC21P0019500
Assignment Date	: 01/08/2022	Excess	: S\$500.00
Date of Inspection	: 02/08/2022	Est. Duration of Repair	: 0
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (HQ) BLK 6 WOODLANDS ROAD 399F,, YEW TEE IND ESTATE SINGAPORE 678006		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	Total Loss
Revised Amount	:S\$	Total Loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	126,000.00
COE / PARF Rebate	:S\$	54,353.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,647.00

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Vehicle recommended Total Loss  
Pending for investigation