

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 06/08/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHF288K
Case Reference Number	TAX/07/22/2094
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SIM KAY TOH
Type of Accident	Side Swipe
Accident Date and Time	29/7/2022 12:30 PM
Accident Reported Date and Time	29/7/2022 3:42 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115755
Special Instruction to ARC, if any	TP/RIGHT FRONT PORTION/NTUC - LKK
Prepared Date and Time	30/7/2022 10:43 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$378.00	\$200.00
Total Spare Part Cost	\$9,026.42	\$672.80
Total Other Cost	\$380.00	(\$222.80)
TOTAL COST	\$10,460.42	\$950.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	30/07/2022 10:55 AM	01/08/2022 5:20 PM
Signature		
Remarks		resurvey after repair/ lump sum repair

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2208-0082	Invoice Number	
Quotation Date	06.08.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$378.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$222.80)
Total Other Costs	\$380.00	(\$222.80)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		52127-47911	COVER, FR BUMPER RH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given
		52128-47910	COVER, FR BUMPER LH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given
		52114-47270	BRACKET, FR BUMPER	0.00	\$110.50	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Check
		53395-47060	SEAL, HOOD TO FR END	0.00	\$85.50	0.00	\$0.00	Replace	Not Given
		53112-47310	GRILLE, RADIATOR	1.00	\$178.60	25.00	\$133.95	Replace	Replace
		53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Check
		75310-33050	EMBLEM ASSY FRONT	1.00	\$105.80	25.00	\$79.35	Replace	Replace
		53111-47140	GRILLE, SUB -ASSY , 2	0.00	\$160.50	0.00	\$0.00	Replace	Check
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$8.80	0.00	\$0.00	Replace	Not Given
		52421-47030	PAD, FRONT BUMPER (NO.1)	0.00	\$40.70	0.00	\$0.00	Replace	Check
		52421-47040	PAD, FRONT BUMPER (NO.2)	0.00	\$36.00	0.00	\$0.00	Replace	Check

✓
X
X
X
X
X
X
✓
X
X
✓
X
✓
X
X
X
✓
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/08/2022

User ID : PohSuan

		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X
		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given	X
		52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Not Given	X
		52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
		52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
		52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Not Given	X
		52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Not Given	X
		81145-47890	UNIT, HEADLAMP, RH	0.00	\$2,637.60	0.00	\$0.00	Replace	Not Given	X
		81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given	X
		81210-12240	LAMP ASSY, FOG, RH	0.00	\$237.10	0.00	\$0.00	Replace	Check	X
		81935-47070	CORD, FOG LAMP	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
		51443-12110	COVER, ENGINE UNDER SIDE RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
Total					\$10,589.30		\$672.80			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	672.80	
+	300.00	L/S \$950/-
+	200.00	
	<u>1,172.80</u>	
	-20%	
	<u>938.24</u>	