

COMFORTDELGRO ENGINEERING PTE LTD

(SAS-KIV)

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 27.06.2022

MODEL: Hyundai i40

INSURANCE: NTUC (LKS)

VEHICLE NO.: SHC8200B

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Side Bracket LH	1		\$ 22.40
	Front Fender LH	1		\$ 663.00
	Front Fender Shield LH	1		\$ 174.90
	Front Fender Retainer LH	1		\$ 217.20
	HeadLamp LH	1		\$ 1,388.00
	Front Wheel Cap LH	1		\$ 217.20
	Headlamp Support Panel	1		\$ 907.40
	Wing Mirror LH	1		\$ 670.00
	SUB TOTAL			\$ 5,334.30
	LESS 20%			\$ 1,066.86
	DISCOUNTED TOTAL			\$ 4,267.44
	Frt Wheel Tyre LH	1	SVC	\$ 216.00
	Labour Charge			
	Panel Beating - Rear Fender LH etc			\$ 1,200.00
	Spray Painting Charge - Rear Fender LH etc			\$ 1,200.00
	Check Lightings			\$ 40.00
	Tuff Kote			\$ 40.00
	Wheel Alignment			\$ 120.00
	Towing Fee			-
	TOTAL LABOUR			\$ 2,600.00
	ESTIMATE TOTAL			\$ 7,083.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 92495749
 WP, 27/6/22 C450
 C/B Rising after repair
 Tanpin C. Lkhanto. wu
 26 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

S
E