## MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

ehicle No. : SHB6600Z

Make

: HYUNDAI

Model

: IONIQ(G3)

Date: 27.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
15-14	REAR BUMPER COVER	PROBLET C A CHIEF	The state of the s	· Ry \$459.40
	REAR BUMPER CLIPS			ACC \$22.00
	REAR BUMPER CENTRE MOULDING ASSY			de \$451.25
	REAR BUMPER LOWER CTR MOULDING			\$155.00
0				× \$40.50
	ANTENNA SMARTKEY			× \$201.5
1	REAR BUMPER FOG LAMP			
	SUB TOTAL	1	100.06	\$1,329.6
	LESS 20%		475.25	\$265.9
	DISCOUNTED TOTAL		473.25 378.60	\$1,063.7
	DISCOUNTED TO WE		3940	1010.1
	DEAD DUMBED BURDED MAT			MUX \$50.0
	REAR BUMPER RUBBER MAT		-/	en \$55.0
	REAR NUMBER PLATE WITH TRIM COVER		55	NMX \$180.0
÷	REAR BUMPER REVERSE SENSOR	*		\$285.0
š	Labour Charge			350 5600
	PANEL BEATING			φυσυ.
	SPRAY PAINTING CHARGE			250 \$300.
	CHECK ALL LIGHTING		630	NNX \$60.
	REMOVE/REFIX REVERSE SENSOR			BO \$80.
	TOTAL LABOUR		1063,60	\$1,040.
	ESTIMATE TOTAL		1063,60 454850 20days	\$2,388.
			20101	
			2 Zoungs	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylin 97497497

inpo 2766/27 C 430

«2 days

notify Lls Rising affer report

resurvey feathin Chhandon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: