

ASS. REC. BY: Taufik

REF:

NS/ NC 22007325/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **FBH 2449K**

Policy No. _____


Claims No. **MT/1177840-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Loh

Vehicle: IN / OUT

Veh No: **SHB66 00Z** Yr Regn: **2019, Jg**Type: M.Car / M.Cycle / Bus / Van / Lorry / Van / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 389605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851CKY164987Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 215/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Worhake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/6/2022 D.O.I. 27/6/22Survey held at Conf A LohDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/8/22 Taufik confirmed LS \$850 (Red 1538.72, 64%)

TP-INC-FBH 2449K.

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 31/8/22-typist

Rep. Format: **TP**Lump Sum / LS: **\$850**Days Of Repair: **2**Resurvey No. of Trip: **1**Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

REPAIR ESTIMATE

Model : IONIQ(G3)

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanghin 92495709
in 27/6/22 @ 430

6 2 days

4/5 Rising after repeat
fasting cholesterol

Date:

Date/Time: 27.06.2022 12:48

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299641

JC NO 305521143

CUSTOMER

MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO:

SHB6600Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

27.06.2022 09:25

DATE/TIME IN

YR OF MANU.

17.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164944

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 26.06.2022

NATURE: 3P 26.06.2022

S/NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

SHB6600Z

YY

Exit Pass

Vehicle No.:

SHB6600Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard