

ASS. REC. BY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

WP
ms lobeVeh No: SHD 6876JYr Regn: 2022 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prioc.c 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 42515

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD PCB3FY 903093811Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wan Huan

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 27/6/22Survey held at Garage Logue

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP-INC-GBG5916P

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI. _____

Photos _____

Others _____

TOTAL

REPAIR ESTIMATE

Model : Prius

MVA: MS. LOKE YY

Tamplin 9749549
WP' 28/6/77 2430
R/R P/P Romy before paint
o2 days
tamplin C unknown

Acknowledged by Repairer
Signature: _____
Date: _____

Date/Time: 27.06.2022 15:35

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299710


JC NO 305521309

STOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 .. (R) 65508755 (O) (P) COUNT CARD NO.	REGN NO: SHD6876J	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4A27)	DATE/TIME IN 06.2022 12:05
	YR OF MANU. 24.03.2022	TARGET DATE
	CHASSIS CODE JTDKB3FU903093811	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.06.2022
NATURE: 3P 27.06.2022

3/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ement Slip

Exit Pass

SHD6876J

YY

Vehicle No.:

SHD6876J

vice Advisor

Signature/Date

Name of Service Advisor

Date

rd to Service Reception upon collection

To be kept by Security Guard