COMFORTDELGRO ENGINEERING

Our J	ob Ref	No :	305520981			EI 10II 1EEIXII 10
Date			30.06.22		59	mfortDelGro Engineering Pte Ltd Loyang Drive Singapore 508969 x: 6546 8156
FINA	LIZATI	ON FORM				
То	: _		LKK		Fax	E.
Attn	: M					
Vehic	le Reg	No. SHA	1247D	Date	e of Accident	t:24.06.22
The s	urvey	and estimates of	the repairs of the above-me	ntioned vehicl	e are as folic	ows:-
1.	The r	epair job shall bil	l to:	NTUC		WB 9504X
2.	The fi	nalized amount s	shall be:			
	(a)	Spare Parts after	er List discount			
	(b)	Labour Charges	3			
	` '	Total for Part-E	By-Part Repair Cost			9
	(c.)		ir (if applicable) um repair cost after Less; n Repair cost	20%		\$10,500.00
3. 4.	We si	ated normal perional treat the aboundary	od for repairs:		orking days. f there is no	o reply from you within
5.	Thank	you for your ass	sistance.		e confirm the alized amou	e estimates and nt
	Signat	ture:	M	_ Się	gnature: _	taufikh
	Name	JUMANI		Na	me : <u>T</u>	AUFIKH
	Tel	: 6214831	5	Da	ite : _	31/8/22
	Fax	: 6546815	6	_		
For O	fficial	Use Only				
	ŀ	tem	Amount	Document Attached Yes or No	Confirm By (Signature)	
Rental Rate P/Day				YES		
2. Loss of Income Paid			****	NO		
3. Survey Fees			****	() ###		
5. Me	dical F	ch Fee ees (on behalf f applicable)	\$7.49 / \$2.00	YES		
Remar	ks:	-				



VEHICLE NO.	SHA4247D	TYPE OF CASE	:	NTUC
JOBCARD NO.	305520981	SURVEY BY	:	LKK-TAUFIKH
ACC.DATE	24.06.22	DATE		

DESCRIPTION	QTY	ESTIMATE	REMARKS
COVER - RAD,GRILLE UPPER	1	\$318.80	LIST de
GUARD - AIR RAD.UPPER	1	\$127.50	dis
AIR CLEANER ASSY	1	\$1,336.50	cra
RAD.COOLANT	1	\$45.00	nec
		\$ 185± 80	
CHECK ITEM			
HEADLAMP ASSY RH		\$2,110.30	
HEADLAMP ASSY LH		\$2,110.30	
FRT BUMPER ASSY		\$476.30	
RADIATOR ASSY		\$510.50	
RADIATOR BLOWER MOTOR		\$1,459.50	
AIR DUCT		\$96.80	
AIR DUCT - B		\$158.00	
CONDENSOR		\$663.60	
LABOUR			
	TOTAL:		JUMANI