

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH9686U

31.07.2022

MAKE REG 19.07.2017

CHIANG/ NTUC

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER		all \$503.04
1	REAR BUMPER SIDE RETAINER RH		net \$112.70
1	REAR BUMPER LOWER COVER		cut \$654.96
1	REAR BUMPER UNDER SIDE RH		? \$232.00
1	REAR BUMPER REINFORCEMENT		X \$378.32
10	REAR BUMPER CLIPS	\$2.20	net \$22.00
1	TAIL LAMP RH UPP		net \$557.90
1	TAIL LAMP RH LOW		cut \$570.00
	SUB TOTAL		\$3,030.92
	25.00%		\$757.73
	DISCOUNTED TOTAL		\$2,273.19
1	REAR REVERSE SENSOR		X \$135.70
1	REAR BUMPER MAT		net \$50.00
1	REAR BUMPER ADVERTISEMENT		net \$50.00
2	REAR FENDER ADVERTISEMENT	\$100.00	net \$200.00
1	BOOTLID COMFORT APP		X \$40.00
1	BOOTLID COMFORT/TEL NO STICKER		X \$60.00
			\$462.13
	Labour Charge		
	Panel Beating		350 \$850.00
	Spray Painting Charge		500 \$600.00
	Remove/Refix Upholstery rear		X \$60.00
	Tuff Kote		X \$60.00
	Check Lighting		30 \$60.00
	TOTAL LABOUR		\$1,885.00
	ESTIMATE TOTAL		\$4,620.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495749
 in 18/7/2022
 2 days
 L/S Nishu app upon
 Tanji M. Chhauto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4493791

JC No: 905525035

STOMER

MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


COUNT CARD NO.

REGN NO.: SH 9686U	MILEAGE
MAKE : TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)01.08.2022	DATE/TIME IN 09:30
YR OF MANU. 19.07.2017	TARGET DATE
CHASSIS CODE JTDKB3FU303561466	COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 31.07.2022
NATURE: 3P 31.07.2022

NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip
No.: **SH 9686U** **CHIANG**

Signature/Date
Returned to Service Reception upon collection

Exit Pass
Vehicle No.: **SH 9686U**

Name of Service Advisor _____
Date
To be kept by Security Guard