

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB4478Z

30.07.2022

MAKE REG: 20.12.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

| Qty | Parts Description/ Labour | Unit Price | Amount |
|--|-----------------------------|----------------|-------------------------|
| 1 | REAR BUMPER COVER | | R \$553.00 |
| 1 | REAR BUMPER LOWER COVER | | X \$228.00 |
| 1 | REAR BUMPER REINFORCEMENT | | X \$428.40 |
| 10 | REAR BUMPER CLIPS | \$2.20 | u X \$22.00 |
| 2 | REAR BUMPER BRACKET LH/RH | \$35.60 | X \$71.20 |
| 2 | REAR BUMPER REFLECTOR LH/RH | \$32.00 | X \$64.00 |
| | SUB TOTAL | | \$1,366.60 |
| | 20.00% | | \$273.32 |
| | DISCOUNTED TOTAL | | \$1,093.28 |
| 1 | REAR BUMPER MAT | | u X \$50.00 |
| 1 | REAR REVERSE SENSOR | | u X \$135.70 |
| | | | \$167.13 |
| | Labour Charge | | |
| | Panel Beating | 280 | \$450.00 |
| | Spray Painting Charge | 250 | \$300.00 |
| | Remove/refix reverse sensor | 30 | \$60.00 |
| | Check Lighting & Wiring | u X | \$40.00 |
| | TOTAL LABOUR | \$560 | \$850.00 |
| | ESTIMATE TOTAL | 2 days | \$1,943.28 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | |

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanji 97495749
 WP 1/8/77C 5pm
 2 days
 1/5/2022 after repair
 Tanji elluhandan