

ASS. REC. BY: Taufik

REF:

NS/ INC 22007333/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKB 7783L

Policy No. _____

Claims No. MT/1182389-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	☒

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Alway Vehicle: IN / OUTVeh No: SHS4478Z Yr Regn: 2012 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai 140 C.C. 1685Colour BLUE A/C: Insured / Std / NI / NASp. Reading 561174 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB414M144100007

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wetake

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/7/2022 D.O.I. 1/8/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/9/22 Taufik informed final fig \$560 (Red 1383.28, 71%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 26/9/22-typist

Rep. Format: TPLump Sum / L.B.I. (\$) \$560Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Date/Time: 01.08.2022 12:50

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4493537

JC NO: 305525031

ISTOMER

3/MS COMFORT TRANSPORTATION PTE LTD

ISTOMER NO. 7010045

IDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

L. (R) 65508755

(O)

(P)

3COUNT CARD NO.

REGN NO:

SHB4478Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

01.08.2022 10:25

DATE/TIME IN

YR OF MANU.

20.12.2017

TARGET DATE

CHASSIS CODE

KMHLB41UMHU100007

COMPLETION DATE/TIME:

JOB DESCRIPTION


ccident Date: 30.07.2022

ATURE: 3P 30.07.2022

/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:

0.:

le No.: SHB4478Z

CHIANG

Vehicle No.:

SHB4478Z

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB4478Z

30.07.2022

MAKE REG: 20.12.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Rx \$553.00
1	REAR BUMPER LOWER COVER			X \$228.00
1	REAR BUMPER REINFORCEMENT			X \$428.40
10	REAR BUMPER CLIPS		\$2.20	Rx \$22.00
2	REAR BUMPER BRACKET LH/RH		\$35.60	X \$71.20
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	X \$64.00
	SUB TOTAL			\$1,366.60
	20.00%			\$273.32
	DISCOUNTED TOTAL			\$1,093.28
1	REAR BUMPER MAT			X \$50.00
1	REAR REVERSE SENSOR			? \$135.70
				\$167.13
	Labour Charge			
	Panel Beating		280	\$450.00
	Spray Painting Charge		250	\$300.00
	Remove/refix reverse sensor		30	\$60.00
	Check Lighting & Wiring		X	\$40.00
	TOTAL LABOUR			\$850.00
	ESTIMATE TOTAL			\$1,943.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanji 97425249
WP 1/8/770 5pm
2 days
1/5/2022 at repair
Tanji ekkharan