

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305525031

Date : 05.08.2022

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

## FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHB4478Z

30.07.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC SKB7783L

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges \$560.00

**Total for Part-By-Part Repair Cost \$560.00**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Signature : 

Name : CHIANG

Name : Taufikh

Tel : 62148314

Date : 26/9/22

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305525031  
REGN NO : SHB4478Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 01.08.2022 10:25  
ACCIDENT DATE : 30.07.2022

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

SUB-TOTAL : 0.00

## JOB NATURE

0000 PB PANEL BEATING SHB4478Z TP 280.00  
0001 SP SPRAYPAINT CHARGE 250.00  
0002 20-22 REMOVE/REFIX REVERSE SENSOR 30.00

SUB-TOTAL : 560.00

TOTAL : 560.00

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :