

Taught

INC

1997

Veh No: SHD8604P Yr Regn: 2018 Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai coupe C.C. 1550

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 500923 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HCSTICVKA/21906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

	
N/S	O/S

Tyre Size: F: 195/63R15

R: 7 7

BS / DIUN / EYNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOXO LYXKO 21 1462 H26.

TOYO / YOKO BI

Front Rear

R/Bal.	mm	R/Bal.	6	mm
--------	----	--------	---	----

1/2 Bal 1/2 Bal

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

$$S + RS \rightarrow S$$

Photos

1 Others

TOTAL

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD8604P

29.07.2022

MAKE REG. 11.12.2015

MODEL IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER LOWER MOULDING			\$155.00
1	REAR BUMPER UNDER CENTRE COVER			\$225.00
1	BOOTLID COVER			\$2,549.70
1	BOOTLID LOCK UPPER			\$224.00
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	BUMPER FOG LAMP			\$201.50
2	BUMPER NUMBER LAMP LH/RH		\$85.30	\$170.60
1	BUMPER HOOK COVER			\$94.60
1	REAR ANTENNA – SMART KEY			\$40.50
1	REAR END PANEL			\$532.00
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60
				\$6,002.25
				20.00%
				\$1,200.45
				DISCOUNTED TOTAL
				\$4,801.80
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	BOOTLID ADVERTISEMENT			\$100.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00	\$200.00
2	SEALANT WSCREEN		\$23.00	\$46.00
1	REAR NUMBER PALTE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$647.50
	Labour Charge			
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$600.00
	Remove/Refix rear windscreen UPP/LOW			\$200.00
	Check wiring and lighting			\$60.00
	Tuff Kote			\$60.00
	Remove/Refix reverse sensor			\$60.00
				\$2,030.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$7,479.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97445749

wp' 11/8/22 27pm

1/3 Resurvey After repair

3 days

taufik@lkhart.com

Date/Time: 29.07.2022 16:40 Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4474669

JC NO: 505524972

CUSTOMER
CITYCAB PTE LTD
7010070
CUSTOMER NO.
383 SIN MING DRIVE
Singapore SINGAPORE 575717
ADDRESS
65551188
L. (R) (O)
(P)


REGN NO: SHD8604P	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 29.07.2022 14:40
YR OF MANU. 11.12.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU121906	COMPLETION DATE/TIME:

SCOUT CARD NO.

JOB DESCRIPTION

Accident Date: 29.07.2022
ATURE: 3P 29.07.2022

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

By: _____
On: _____
Vehicle No.: **SHD8604P** **CHIANG**

Vehicle No.: **SHD8604P**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard