

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007337/TVY3Q2**Date:** 12/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011472100

Claimant Vehicle No : SBQ128C **Insured Vehicle No :** SNB8278L

Date of Loss: 29/07/2022 Nature of Claim: TP Claim No: SNM22D205349/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBQ128C**

Make & Model: MERCEDES-BENZ C200, 1.8 (A) Engine No: 27492030214993

Reg. Date: 31/12/2014 (Man. Year: 2014) Chassis No: WDD2050422F046620

Colour: Silver Odometer: 143633 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,861.26	5,930.21	8,931.05	60.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	910.00	3,240.00	78.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,011.26	6,840.21	12,171.05	64.02
Approved Total (Overridden) (S\$)		5,450.00		
Nett Amount (S\$)	19,011.26	5,450.00	13,561.26	71.33

INSPECTION

Date of Assignment: 12/08/2022

Date Inspected: 11/08/2022 Inspected At: JEW Motors (HQ)
60 Jalan Lam Huat Carros Centre #03-72
Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	143	MERCEDES-BENZ C200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBQ128C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,674.18 FL	*1,674.18 FL
2	1		*FRONT BUMPER BASIC MOUNTING RH	Deformed	85.01 FL	*85.01 FL
3	1		*FRONT BUMPER GRILLE RH	Not Necessary	61.35 FL	*- FL
4	1		*FRONT BUMPER GRILLE CENTRE	Not Necessary	125.09 FL	*- FL
5	1		*FRONT BUMPER LOWER TRIM MOULDING	Not Necessary	178.68 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	154.81 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	420.14 FL	*- FL
8	1		*FRONT BUMPER SIDE DISTANCE SENSOR RH	Not Working	172.07 FL	*172.07 FL
9	1		*FRONT BUMPER DISTANCE SENSOR (4 PCS)	Not Working (1 PCS ONLY)	688.28 FL	*172.07 FL
10	6		*FRONT BUMPER PRS SPACER RING	Necessary	38.52 FL	*38.52 FL
11	1		*FRONT PTS ELECTRICAL WIRING HARNESS	Not Necessary	148.55 FL	*- FL
12	1		*FRONT HEADLAMP ASSEMBLY RH	Cut	3,443.48 FL	*3,443.48 FL
13	1		*FRONT HEADLAMP ASSEMBLY LH	Not Necessary	3,443.48 FL	*- FL
14	1		*RADIATOR GRILLE AIR DUCT	Not Necessary	128.30 FL	*- FL
15	1		*RADIATOR GRILLE TRIM	Not Necessary	209.42 FL	*- FL
16	1		*RADIATOR GRILLE ORNAMENTAL MOLDING RH	Not Necessary	77.31 FL	*- FL
17	1		*RADIATOR GRILLE ORNAMENTAL MOLDING LH	Not Necessary	77.31 FL	*- FL
18	1		*RADIATOR GRILLE MERCEDES STAR CARRIER	Not Necessary	72.06 FL	*- FL
19	1		*RADIATOR GRILLE MERCEDES STAR	Not Necessary	135.19 FL	*- FL
20	1		*FRONT BONNET	Not Necessary	2,155.25 FL	*- FL
21	1		*FRONT BONNET EMBLEM	Not Necessary	87.83 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Necessary	782.43 FL	*- FL
23	1		*FRONT SUPPORT PANEL CONSOLE	Not Necessary	258.24 FL	*- FL
24	1		*FRONT FENDER RH	Bent	970.46 FL	*970.46 FL
25	1		*FRONT FENDER LINER RH	Not Necessary	136.18 FL	*- FL
26	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
27	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*SET FRONT BUMPER GRILLE CENTRE CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*SET FRONT BUMPER GRILLE RH CLIPS	Not Necessary	20.00 FS	*- FS
30	1		*SET RADIATOR GRILLE ASSEMBLY CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET FRONT FENDER LINER RH CLIPS	Not Necessary	40.00 FS	*- FS
33	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*FRONT FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
35	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,433.62	6,585.79
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,572.36	655.58
Total Parts (\$\$)	14,861.26	5,930.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,200.00	450.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	30.00
5	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New	150.00	0.00
6	TO REMOVE & REFIX RADIATOR & CONDUCT PRESSURE TEST	New	150.00	0.00
7	TO REMOVE & REFIX FRONT HEADLAMP WITH FOCUS ADJUSTMENT	New	250.00	0.00
8	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
9	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT .PROGRAMMING & CABIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			4,150.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >