

J.E.W Motor Pte Ltd

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : SBQ 128C
 Made : Mercedes Benz
 Model : C200
 Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 1,674.18	\$ 1,674.18 ✓
2	Front Bumper Basic Mounting RH	1	\$ 85.01	\$ 85.01 ✓
3	Front Bumper Grille RH	1	\$ 61.35	\$ X nn 61.35
4	Front Bumper Grille Centre	1	\$ 125.09	\$ X nn 125.09
5	Front Bumper Lower Trim Moulding	1	\$ 178.68	\$ X nn 178.68
6	Front Bumper Sponge	1	\$ 154.81	\$ X nn 154.81
7	Front Bumper Reinforcement	1	\$ 420.14	\$ X nn 420.14
8	Front Bumper Side Distance Sensor RH	1	\$ 172.07	\$ nn 172.07 ✓
9	Front Bumper Distance Sensor	1	\$ 172.07	\$ nn 172.07 ✓
10	Front Bumper PTS Spacer Ring	6	\$ 6.42	\$ nn 38.52 ✓
11	Front PTS Electrical Wiring Harness	1	\$ 148.55	\$ X nn 148.55
12	Front Headlamp Assembly RH	1	\$ 3,443.48	\$ nn 3,443.48 ✓
13	Front Headlamp Assembly LH	1	\$ 3,443.48	\$ X nn 3,443.48
14	Radiator Grille Air Duct	1	\$ 128.30	\$ X nn 128.30
15	Radiator Grille Trim	1	\$ 209.42	\$ X nn 209.42
16	Radiator Grille Ornamental Molding RH	1	\$ 77.31	\$ X nn 77.31
17	Radiator Grille Ornamental Molding LH	1	\$ 77.31	\$ X nn 77.31
18	Radiator Grille Mercedes Star Carrier	1	\$ 72.06	\$ X nn 72.06
19	Radiator Grille Mercedes Star	1	\$ 135.19	\$ X nn 135.19
20	Front Bonnet	1	\$ 2,155.25	\$ X nn 2,155.25
21	Front Bonnet Emblem	1	\$ 87.83	\$ X nn 87.83
22	Front Support Panel	1	\$ 782.43	\$ X nn 782.43
23	Front Support Panel Console	1	\$ 258.24	\$ X nn 258.24
24	Front Fender RH <i>aluminium</i>	1	\$ 970.46	\$ nn 970.46 ✓
25	Front Fender Liner RH	1	\$ 136.18	\$ X nn 136.18

6555.79
 -10%
 5900.21

10%

Parts Sub Total :	\$ 15,723.62
Discount	\$ 1,572.36
PARTS TOTAL :	\$ 14,151.26

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X nn 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 30 net 50.00

3	Front Bumper Grille Centre Clips - Set	1	\$	30.00	\$	X nn	30.00
4	Front Bumper Grille RH Clips - Set	1	\$	20.00	\$	X nn	20.00
5	Radiator Grille Assembly Clips - Set	1	\$	50.00	\$	X nn	50.00
6	Front Bonnet Insulator Clips - Set	1	\$	50.00	\$	X nn	50.00
7	Front Fender Liner RH Clips - Set	1	\$	40.00	\$	X nn	40.00
8	Front Bonnet Sealant	1	\$	150.00	\$	X nn	150.00
9	Front Fender RH Sealant	1	\$	150.00	\$	X nn	150.00
10	Radiator Coolant	1	\$	120.00	\$	X nn	120.00
30					SPECIAL NETT TOTAL :		\$ 710.00

Nos.	LABOUR	TOTAL \$	
1	To Panel Beat, Remove & Refix Parts	\$ 400	1,600.00
2	To Spray Paint Affected Areas	\$ 450	1,200.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To apply anti rust on affected parts	\$ 20	120.00
5	To Remove & Refix Aircon Condenser & Top Up Gas	\$ X	150.00
6	To Remove & Refix Radiator & Conduct Pressure Test	\$ X	150.00
7	To Remove & Refix Front Headlamp with Focus Adjustment	\$ X	250.00
8	To Conduct Water Leak Test	\$ X	100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
910 LABOUR TOTAL :		\$	4,150.00

Taufik 97495749
WP' 2/3 Resurvey after repair
11/8/22 @ 5pm

03 days
taufik elkhantaw.
To check consistency of accident
To check part price

PARTS TOTAL : \$ 14,151.26
SPECIAL NETT TOTAL : \$ 710.00
LABOUR TOTAL : \$ 4,150.00
GRAND TOTAL : \$ 19,011.26

6840.21

L/S - 5472.16
= 5450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____