

ASS. REC. BY:

REF:

C12 / 22007338/K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GZ 8855C

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyna

c.c

2882

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

153741

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFA T35Y 90K 208403

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: JK

195R15X8

R: Conda

155R12X80D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

9

mm

L/Bal.

7

mm

L/Bal.

9

mm

D.O.A.

24/7/2

D.O.I.

10/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Fines

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

ump Sum / I.B.I: (\$

2)

清河

CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(SFV6880A)
Policy No:		Date of Loss:	24/07/2022
Vehicle Reg. No.:	GZ8855C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	VEERASAMY ROOSVELI	Driver (Insured):	FONG THIANG WANG
Make/Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Vehicle Reg. Date:	18/08/2017
Vehicle Colour:	WHITE		
Engine No:	1KD2723868	Chassis No:	JTFAT35Y90K208403
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

*Not Whistle
6/1/2023
Repair After Paint
7 days*

Remarks: VEHICLE CURRENTLY LYING AT WOODLANDS WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	2,283.00
Miscellaneous Items	419.00
Labour	2,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,672.00
+ GST 7.00% (\$\$)	397.04
Nett Amount (\$\$)	6,069.04

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Source: (Last Synchronised: 08 Aug 2022)
 Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GZ8855C)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*240.00 F ✓
2	1		*1 PC FRT PANEL	0.00	0.00	*420.00 F ✓
3	1		*1 PC FRT PANEL EMBLEM (DYNA)	0.00	0.00	*35.00 F ✓
4	1		*1 PC TAILGATE	0.00	0.00	*520.00 F ✓
5	1		*1 PC TAILGATE STICKER (DYNA)	0.00	0.00	*18.00 F ✓
6	1		*1PC AIR-CON EVAPORATOR	0.00	0.00	*1,050.00 F x
Total Parts (\$\$)						2,283.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC FRT NUMBER PLATE	25.00 ✓
2	1	1 PC REAR STEP TRAY	150.00 ✓
3	1	1 PC STICKER - 13 PAX	10.00 ✓
4	1	1 PC STICKER - 70KM/H	10.00 ✓
5	1	1 SET REVERSE SENSOR	200.00 ✓
6	1	12 PCS TAILGATE RIVETS @2/PC	24.00 ✓
Sub Total (\$\$)			419.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX TAILGATE, REAR STEP TRAY, TRANSFER TAILGATE INNER PROTECTOR, KNOCK & REPAIR REAR LH CORNAL PILLAR AND REALIGN THE SAME	New	400 450.00 ✓
2	PUTTY & RESPRAY ON TAILGATE, STEP TRAY, REAR LOWER MEMBER	New	400 450.00 ✓
3	REMOVE & REFIX FRT WINDSCREEN GLASS	New	60.00 ✓
4	REMOVE & REFIX DASHBOARD, METER AND CHECK WIRING	New	250 280.00 ✓
5	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00 ✓
6	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, CHECK HEADLAMPS, TO CUT, WELD & RENEW FRT PANEL AND REALIGN THE SAME	New	600 680.00 ✓
7	PUTTY & RESPRAY ON FRT PANEL, GRILLE, FRT BUMPER	New	500 600.00
8	TO REWRITE ADVERTISEMENT	New	(Bill) 350.00 ?
Gross Labour Cost (\$\$)			2,970.00


Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Describe Circumstance of the Accident

NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (☒) Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



I am went to Gerangan Towards to Jalan Basar Turning Right to Veerasamy Road in front Zebra crossing there is zebra near in front Stop vehicle is 49. 2nd vehicle also stop and also stop in turn stop. Then a few seconds (5-6) behind vehicle Car number SFV-6880A hit on to my vehicle behind and push my vehicle forward and hit on too front vehicle Car number - G BB-2852K. There was no injury all parties.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Rosvethi

25/7/22

25/7/22

Ethudg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/07/2022 19:08 (SGT)
Reported by	Driver
Date of Accident	24/07/2022 12:37 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JLN BESAR TURN RIGHT TOWARDS VEERASAMY RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ8855C
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BESTCOAT CONTRACT SERVICES PTE LTD
Company Reg No	1XXXXX291N
Email Address	exec@bestcoat.com.sg
Mobile Phone No	(Phone) +65-67523008
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	DYNA 150 5MT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00086002204

DRIVER

Name of Driver	VEERASAMY ROOSVELI
Passport No/FIN	FXXXX064U
Date Of Birth	12/05/1976
Occupation	Outdoor