

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 30 Aug 2022

Preliminary Advice

Insured	: SFV6880A		
Vehicle No			
TP Vehicle	: GZ8855C	Accident Date	: 24/07/2022
No			
Make	: TOYOTA DYNA 150	Assignment Date	: 11/08/2022
Date of	: 10/08/2022	Est. Duration of	: 7
Inspection		Repair	
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN)		
	BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A		
	SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,672.00
Revised Amount	:S\$	4,162.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,162.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.