

2022 8:59am SLP Fax

RECEIVED 02/08/2022 16:56
64841482

p.1

*Not Authorized
11 Rm @ 3900hr
Presumably After Rain
6 days*

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd	DATE	03.08.2022
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SKX 9201 X
Singapore 079909	MAKE	Mazda 3

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : GBF 6038 Y

Pc	Pcs	JM6BM42A8G0328491	UNIT PRICE	AMOUNT
		Recommended Parts		
1	pc	Front right side fender <i>350.60</i>	<i>As</i>	\$406.00
1	pc	Front right side fender inner cowling <i>175.10</i>	<i>As</i>	\$219.20
8	pc	Front left side fender inner cowling clips	\$4.00	\$32.00
1	pc	Front right side door <i>1021</i>	<i>As</i>	\$1,201.00
1	pc	Front right side door inner board	<i>As</i>	\$1,012.00
10	pcs	Front right side door inner board clips	\$5.00	\$50.00
1	pc	Front right side door chrome protector (upper)	<i>As</i>	\$81.00
1	pc	Front right side door rubber	<i>As</i>	\$112.00
1	pc	Front right side door vertical black sticker	<i>As</i>	\$68.00
1	pc	Front right side door horizontal black sticker	<i>As</i>	\$81.00
1	pc	Front right side door gear	<i>As</i>	\$126.00
1	pc	Front right side door gear motor	<i>As</i>	\$149.00
1	pc	Front right side door channel	<i>As</i>	\$174.00
1	pc	Front right side door top hinge	<i>As</i>	\$45.00
1	pc	Front right side door lower hinge	<i>As</i>	\$42.00
1	pc	Front right side door stopper	<i>As</i>	\$8.00
1	pc	Front right side door outer mirror assy	<i>As</i>	\$726.00
1	pc	Rear right side door	<i>As</i>	\$1,050.00
1	pc	Rear right side door vertical black sticker	<i>As</i>	\$68.00
1	pc	Rear right side door horizontal black sticker	<i>As</i>	\$81.00
1	pc	Rear right side tyre rim	<i>As</i>	\$483.00
1	pc	Rear right side door chrome protector (upper)	<i>As</i>	\$81.00
			<i>208</i>	
			Page 1 of 2	Total

Susan Lim

KENT SENG CAR SERVICES.

TOTAL

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd	DATE	03.08.2022
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SKX 9201 X
Singapore 079909	MAKE	Mazda 3

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBF 6038 Y

Pc	Pcs	JM6BM42A8G0328491	UNIT PRICE	AMOUNT
		Continue from page one.		\$6,295.20
		<u>Recommended Labour</u>		
		Rust-proofing on the rear accident affected		\$150.00 901
		Straightening, repairing and realigning on vehicle right side porton, cutting front right side fender, knocking right side rear fender, dismantle and replace the above mentioned parts.		\$1,200.00 7501
		To respray painting on all accident affected panels, front right side fender, front right side door, rear right side door and rear right side fender.		\$1,200.00 10001
		To transfer door mechanism (F & R door) into new door panel.		\$300.00 1201
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
		Page 2 of 2	Total	\$9,145.20

Susan Lim

KENT SENG CAR SERVICES.