

ASS. REC. BY:

REF:

CT21 2200 7347/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GBF 6038Y

Policy No. DMCVSNW00149402101

Claims No. SNM22D205327/C02/TANCHC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 9201X Yr Regn: 12, 15

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1496

Colour

m. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

113885

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM42A 8G0328491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

30/7/22

D.O.I.

3/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

ols body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/9/22

Kenneth informed LS \$3900 (Red 5245.20, 57%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2) 9/9/22-typist

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + R.S. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: Merimen

Lump Sum / I.B.I: (\$3900

TOTAL

02408.60

DC AUTO

Not Not hain
11 Rmg &
Returning After Rain
6 days

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd	DATE	03.08.2022
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SKX 9201 X
Singapore 079909	MAKE	Mazda 3

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : GBF 6038 Y

Pc	Pcs	JM6BM42A8G0328491	UNIT PRICE	AMOUNT
		Recommended Parts		
1	pc	Front right side fender		<i>As</i> \$406.00
1	pc	Front right side fender inner cowling		<i>P/P</i> \$219.20
8	pc	Front left side fender inner cowling clips	\$4.00	<i>in</i> \$32.00
1	pc	Front right side door		<i>As</i> \$1,201.00
1	pc	Front right side door inner board		\$1,012.00
10	pcs	Front right side door inner board clips	\$5.00	\$50.00
1	pc	Front right side door chrome protector (upper)		<i>in</i> \$81.00
1	pc	Front right side door rubber		\$112.00
1	pc	Front right side door vertical black sticker		<i>in</i> \$68.00
1	pc	Front right side door horizontal black sticker		<i>in</i> \$81.00
1	pc	Front right side door gear		\$126.00
1	pc	Front right side door gear motor		\$149.00
1	pc	Front right side door channel		<i>in</i> \$174.00
1	pc	Front right side door top hinge		<i>in</i> \$45.00
1	pc	Front right side door lower hinge		<i>in</i> \$42.00
1	pc	Front right side door stopper		<i>in</i> \$8.00
1	pc	Front right side door outer mirror assy		<i>Not in</i> \$726.00
1	pc	Rear right side door		<i>As</i> \$1,050.00
1	pc	Rear right side door vertical black sticker		<i>in</i> \$68.00
1	pc	Rear right side door horizontal black sticker		<i>in</i> \$81.00
1	pc	Rear right side tyre rim		<i>in</i> \$483.00
1	pc	Rear right side door chrome protector (upper)		<i>in</i> \$81.00
			Total	

208

Page 1 of 2

Total

Susan Lim

KENT SENG CAR SERVICES.

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd	DATE	03.08.2022
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SKX 9201 X
Singapore 079909	MAKE	Mazda 3

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBF 6038 Y

Pc	Pcs	JM6BM42A8G0328491	UNIT PRICE	AMOUNT
		Continue from page one.		\$6,295.20
		<u>Recommended Labour</u>		
		Rust-proofing on the rear accident affected		\$150.00 901
		Straightening, repairing and realigning on vehicle right side porton, cutting front right side fender, knocking right side rear fender, dismantle and replace the above mentioned parts.		\$1,200.00 7501
		To respray painting on all accident affected panels, front right side fender, front right side door, rear right side door and rear right side fender.		\$1,200.00 10001
		To transfer door mechanism (F & R door) into new door panel.		\$300.00 1201
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
Page 2 of 2			Total	\$9,145.20

Susan Lim

KENT SENG CAR SERVICES.