

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2001875801-01	Date of Loss:	29/07/2022
Vehicle Reg. No.:	SKW8560X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM CHUN WEI		
Driver:	SIM CHUN WEI		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	18/11/2015
Vehicle Colour:	BLACK		
Engine No:	3ZRB633915	Chassis No:	ZSU600056728
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 0

*Not Authored
Accident After Repair*
@ 2636.00 Ex @ 600h

Remarks: VEHICLE CURRENTLY LYING YISHUN WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

5 days

COST OF CLAIMS

	Amount
Parts	1,996.50
Miscellaneous Items	66.00
Labour	2,090.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	4,152.50
+ GST 7.00% (S\$)	290.68
Nett Amount (S\$)	4,443.18

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)
 Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SKW 8560X

OD/Allianz

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT WINDSCREEN GLASS WITH MOULDING	CNT 0.00	0.00	*700.00 F ✓
2	1		*1 PC LH DOOR SIDE MIRROR	SA 0.00	0.00	*320.00 F X
3	1		*1 PC LH DOOR SIDE MIRROR COVER	SA 0.00	0.00	*45.00 F X
4	1		*1 PC DASHBOARD	SA 0.00	0.00	*750.00 F X
Sub Total (S\$)						1,815.00
+ Margin on L,N Items 10.00% (S\$)						181.50
Total Parts (S\$)						1,996.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC ERP BRACKET	
2	1	1 PC FRT WINDSCREEN GLASS SEALANT	me 26.00 ✓
			me 40.00 ✓
Sub Total (S\$)			66.00

Estimates on Labour

No Particulars

	Lab.Type	Amount
<u>Labour Items</u>		
1 REMOVE & REFIX FRT WINDSCREEN GLASS	New	100.00 ✓
2 REPAIR LH FRONT W/SCREEN PILLAR,BONNET,LH FRONT FENDER AND REALIGN THE SAME	New	550 650.00
3 PUTTY & RESPRAY ON BINNET,FRT LH FENDER,SIDE MIRROR,COVER,LH W/SCREEN PILLAR, TOP ROOF PANEL	New	850 980.00
4 REMOVE & REFIX DASHBOARD	New	250 280.00
5 TO VACUUM & CLEAN UP GLASS SPLINTERS	New	50 80.00
Gross Labour Cost (S\$)		2,090.00

Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES > LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL