

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6202P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S FRONT DOOR (N)	BENT	1,696.40	1,474.10
2	N/S FRONT DOOR HINGE @\$108.10 (N)	TO REPAIR SEE LABOUR	216.20	-
1	N/S FRONT DOOR RUBBER (N)	SERVICEABLE	298.65	-
1	N/S FRONT DOOR OUTER HANDLE (N)	CRACKED	144.10	144.10
1	N/S FRONT DOOR CHECKER (N)	SERVICEABLE	53.70	-
1	N/S FRONT DOOR WEATHER STRIP (N)	SERVICEABLE	172.70	-
1	N/S FRONT DOOR INNER LOCK (N)	TO REPAIR SEE LABOUR	143.20	-
1	N/S FRONT DOOR REGULATOR GEAR (N)	SERVICEABLE	87.30	-
1	N/S FRONT DOOR REGULATOR GEAR MOTOR (N)	SERVICEABLE	458.30	-
1	N/S FRONT DOOR GLASS (N)	SERVICEABLE	633.30	-
1	N/S FRONT DOOR GLASS OUTER MOLDING (N)	SERVICEABLE	113.40	-
1	N/S FRONT DOOR GLASS RUBBER (N)	SERVICEABLE	80.90	-
	LESS 10% DISCOUNT		-409.82	-161.82
			3,688.33	1,456.38
	SPECIAL NETT ITEMS			
1	COMPANY LETTER (SN)	NECESSARY	100.00	25.00
1	ADVERTISE STICKER (SN)	NECESSARY	250.00	60.00
			350.00	85.00
	<u>LABOUR</u>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF N/S FRONT DOOR HINGE AND N/S FRONT DOOR INNER LOCK.		1,200.00	200.00
	TO PUTTY AD RE-SPRAY PAINTING.		1,000.00	200.00
	RE-SEAL ANTI RUST.		200.00	30.00
	TO CHECK WIRING.		80.00	20.00
	TO TRANSFER N/S FRONT DOOR.		120.00	60.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			2,720.00	510.00
	GRAND TOTAL		6,758.33	2,051.38

Report Ref No. CS/LPC22007356/Kcy3e2



Page No.:2 of 2

Report Ref No. CS/LPC22007356/Kcy3e2

KONG SENG CHEONG

**Licensed Appraiser**