



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS/ASM22007366/Aqy3e2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4254H	Veh. Inspected	SLV 6467P
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M047Z5	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	02/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MHFZ28H3300048336	Colour	BRONZE
Odometer	122802 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	HABILEAD	6 mm
L/H Front Tyre	185/60 R15	HABILEAD	6 mm
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/07/2022	Inspection Date	02/08/2022
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	