



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22007372/Uvy3e2 Date: 02/09/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMA 5703M	Veh. Inspected	SMH 7960L
Policy No.		Coverage (\$)	0.00
Claim No.	D22002359MFZH	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	02/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDC1569422J574539	Colour	WHITE
Odometer	42998 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	GOODYEAR	7 mm
L/H Front Tyre	235/50 R18	GOODYEAR	7 mm
R/H Rear Tyre	235/50 R18	GOODYEAR	7 mm
L/H Rear Tyre	235/50 R18	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/07/2022	Inspection Date	08/08/2022
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	