

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMH7960L/2207098

02nd August 2022

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

Date Of Accident : 29th July 2022
Location : Dunearn Road
Third Party Claim Vehicle No : SMA 5703 M
Repair Cost for Vehicle No : SMH 7960 L Mercedes Benz GLA180

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front bumper fascia	1	1,500.00	\$ 1,500.00
2	Front bumper fascia clip	1set	90.00	\$ 90.00
3	Front bumper lower lip	1	969.00	\$ 969.00
4	Headlamp LH	1	2,535.00	\$ 2,535.00
5	Headlamp panel LH	1	990.00	\$ 990.00
6	Headlamp Lh control unit	1	750.00	\$ 750.00
7	Front fender LH	1	820.00	\$ 820.00
8	Front fender garnish LH	1	225.00	\$ 225.00
9	Front fender garnish clip	1	90.00	\$ 90.00
10	Front fender cowling	1	210.00	\$ 210.00
11	Front fender cowling clip	1	90.00	\$ 90.00
12	Front wheel Rim LH(s/nett)	1	993.00	\$ 993.00
13	Front wheel Tyre LH(s/nett)	1	480.00	\$ 480.00
				\$ 9,742.00

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking & welding front fender LH, front fender LH, remove & install all damage parts, straighten & re-align body	\$ 980.00
Tuff-kote on damage parts	\$ 40.00
Spray painting on damage parts	\$ 880.00
Check all lighting after repairs	\$ 40.00
Computerize wheel alignment	\$ 180.00
Labour Charge	\$ 2,120.00
Total Amount	\$11,862.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.