

ASS. REC. BY:

REF:

C11/ 2200-7373K9

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUR 95457

Yr Regn:

08, 17

Type: M. Car / P. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Itanir

c.c

1986

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

74750

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZSU 60 . 0086133

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/7/22

D.O.I.

2/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Est not ready

3/9 11:45 @ 43501 Carhu (Red, 9988.30, 70%)

Date/Time, File Pass to?

1) 8/9/22

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

4350.00

Kg
SQM PTE LTD
 BLK 1003 TOA PAYOH INDUSTRIAL PARK
 # 05-1501 SINGAPORE 319075
 EMAIL : sqm202088@gmail.com H.P 90030857

NOT WITHHOLD
 L1 Sqr 8 4350/0
 RETURNING AFTER PAINT
 5 days

Date : 30 Jul 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE CO-OPERATIVE LTD

CLAIM : THIRD PARTY CLAIM

VEH. No : SLR 9545 Z/ HARRIER

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : LIBERTY INSURANCE

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SMP 1161 Z			

1	TAILGATE 1466-10	\$ B 2,885.00	✓
2	TAILGATE LAMPS	\$ S 580.00	X
1	TAILGATE TRIM BOARD 578	\$ MY CM 788.60	✓
1	TAILGATE LOCK 418	\$ R 560.00	✓
1	TAILGATE LOCK LATCH	\$ R 68.00	X
1	TAILGATE LOCK LOWER SENSOR 185	\$ CM 385.00	✓
1	TAILGATE WEATHERSTRIP	\$ MII/RO 343.80	50/SN
2	TAILLAMPS	\$ S 1,564.00	X
2	TAILLAMP PANELS	\$ R 440.00	X
2	TAILLAMP LOWER BRACKETS	\$ S 280.00	X
1	REAR W/SCREEN MOULDING 190.50	\$ M 220.00	✓
1	HARRIER EMBLEMS	\$ M 98.00	✓
1	TAILGATE CENTER LOGO 66-00	\$ M 120.00	✓
1	END PANEL	\$ R 850.00	X
1	END PANEL TOP GARNISH 361-	\$ MY CM 445.00	✓
1	REAR FLOOR PANEL	REPAIR	
1	REAR BUMPER 866-00	\$ B 1,685.00	✓
2	REAR BUMPER BRACKETS	\$ R 220.00	X
2	REAR BUMPER RETAINERS	\$ S 280.00	X
1	REAR BUMPER LOWER GARNISH 419.	\$ R 980.00	✓
2	REAR BUMPER REFLECTORS	\$ S 330.00	X
1	REAR BUMPER SPONGE 199.00	\$ CM 354.00	✓
1	REAR BUMPER BEAM	\$ RJP 448.00	X

TOTAL PARTS : \$ 13,924.40

LESS 25 % \$ 3,481.10

TOTAL LIST PARTS : \$ 10,443.30

SPECIAL / NETT PARTS

2T	REAR W/SCREEN SEALANT	\$ M 120.00	40/SN
10	REAR BUMPER CLIPS	\$ M 45.00	✓
1SET	REAR BUMPER SENSORS	\$ SHORT 300.00	200/SN

TOTAL S/N PARTS : \$ 465.00

TOTAL PARTS PRICE : \$ 10,908.30

SQM PTE LTD

BLK 1003 TOA PAYOH INDUSTRIAL PARK

05-1501 SINGAPORE 319075

EMAIL : sqm202088@gmail.com H.P 90030857 .

Date : 30 Jul 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE CO-OPERATIVE LTD

ATTN : MOTOR CLAIM DEPARTMENT

CLAIM : THIRD PARTY CLAIM

VEH. No : SLR 9545 Z/ HARRIER

INSURE : LIBERTY INSURANCE

LABOUR CHARGES	AMOUNT	CONDITION
Labour charge to repair, replace , align adjust , remove & refix accident affected area	\$ 1,400.00	500l
To do anti rust	\$ 120.00	30l
To check wiring system, replace sensors	\$ 150.00	70l
Transfer tailgate parts to another tailgate	\$ 140.00	60l
Transfer rear w/screen	\$ 140.00	120l
To do spray painting	\$ 1,200.00	600l
To do computer setting , diganose delete fault code after repair (RESET AUTO TAILGATE AFTER REPAIR)	\$ ~ 280.00	X
TOTAL LABOUR :	\$ 3,430.00	
GRAND TOTAL PARTS & LABOUR :	\$ 14,338.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: