



FALCON-AIR

AHMAD AIZAT BIN AHMAD ZAINI  
C/O 176 SIN MING DRIVE #01-06/07  
SIN MING AUTOCARE 575721

Attention: Motor Claim Department  
Contact: 97776647

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg No: 199501140D  
GST Reg. No: 199501140D

*Not Authorized  
Running B4 paint  
4 days*

*61Pm 81700*

Estimate: ES012417

Date: 04/08/2022  
Vehicle Num.: SMX 1849G  
Make/Model: HONDA CIVIC VTI CVT-2016  
Chassis/Eng#: MRHFC5650GT001228  
Accident Date: 29/07/2022  
Claim No.: SNM22D205326C02  
Reference: TP - AXA AGT CHINA TAIPING  
Policy No.: GA571093

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- |    |      |                           |  |  |
|----|------|---------------------------|--|--|
| 1. | 1 PC | LIST ITEMS:               |  |  |
| 2. | 1 PC | REAR BUMPER <i>617.50</i> |  |  |
| 3. | 1 PC | REAR BUMPER LOWER         |  |  |
| 4. | 1 PC | REAR BUMPER REINFORCEMENT |  |  |
|    |      | BOOT COVER <i>534.10</i>  |  |  |

List Total S\$:  
20.00% Discount S\$:

|           |          |          |
|-----------|----------|----------|
| <i>Am</i> | 617.50   | <i>✓</i> |
| <i>Am</i> | 70.00    | <i>✓</i> |
| <i>Am</i> | 235.00   | <i>✓</i> |
| <i>Am</i> | 554.60   | <i>✓</i> |
|           | 1,477.10 |          |
|           | 295.42   |          |
|           | 1,181.68 |          |

- |    |       |                     |  |  |
|----|-------|---------------------|--|--|
| 1. | 1 SET | SPECIAL NETT ITEMS: |  |  |
|    |       | ASSORTED CLIPS      |  |  |

Special Nett Total S\$:

|           |       |          |
|-----------|-------|----------|
| <i>Am</i> | 60.00 | <i>✓</i> |
|           | 60.00 |          |

LABOUR:  
TO REMOVE/REFIT BOOT COVER MECHANISM  
TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER  
TO REPAIR REAR END PANEL INCLUDING REPLACEMENT OF PARTS  
TO SPRAY PAINT ON BOOT COVER, REAR BUMPER, REAR  
END PANEL

|        |            |
|--------|------------|
| 100.00 | <i>500</i> |
| 50.00  | <i>✓</i>   |
| 550.00 | <i>400</i> |
| 750.00 | <i>400</i> |

Labour Total S\$:

1,450.00

E. & O.E.

Total S\$ : 2,691.68

FALCON AIR AUTO SERVICES PTE LTD

quotation was prepared from visual inspection. Further materials and labour charges may be required when resurvey is conducted. We will advise you accordingly.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg

Lump Sum