



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI22007376/Any3q2

Date: 01/12/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 119G	Veh. Inspected	SNC 3225S
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D22002353MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	02/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA YARIS CROSS	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MXPB102008775	Colour	WHITE
Odometer	27377 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	FALKEN	6 mm
L/H Front Tyre	225/50 R17	FALKEN	6 mm
R/H Rear Tyre	225/50 R17	FALKEN	6 mm
L/H Rear Tyre	225/50 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/07/2022	Inspection Date	02/08/2022
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**