



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22007377/Acy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 13/10/2022

ATTN: CHESTER CHONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 9815R	Veh. Inspected	S 4562CD
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1182483-002	Excess (\$)	0.00
Assign From	DIANA TAY	Assign Date	02/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053AK5004011818	Colour	WHITE
Odometer	124378 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2022	Inspect Date / Time	02/08/2022 (04:51 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------