

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chee So Chow

Date: 04 Aug 2022

## **Preliminary Advice**

Insured Vehicle No	: PC2752U	Accident Date	: 15/07/2022
TP Vehicle No	: SGC394P	Assignment Date	: 02/08/2022
Make	: MAZDA 3	Est. Duration of Repair	: 6 DAYS
Date of Inspection	: 20/07/2022		
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,308.00
Revised Amount	:S\$	6,577.60
Check Items (Estimated)	:S\$	10,525.00
Total	:S\$	17,102.00

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.
- Please note that the preliminary advise amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.