

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708403

Date : 16/07/2022
Vehicle Num. : SGC 394P
Make/Model : MAZDA 3
Chassis/Eng# :
Accident Date : 16/07/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	TAILGATE GLASS MOULDING / <i>MBL</i>		151 00
2.	1 PC	TAILGATE <i>Buc</i>		1,210 00
3.	1 PC	TAILGATE LOGO		78 00
4.	1 PC	TAILGATE EMBLEM - MAZDA / <i>MBL.</i>		58 00
5.	1 PC	TAILGATE EMBLEM - 3		48 00
6.	1 PC	TAILGATE EMBLEM - AXEIA		88 00
7.	1 PC	TAILGATE REFLECTOR / <i>Gar.</i>		395 00
8.	1 PC	TAILGATE LOCK		410 00
9.	1 PC	TAILGATE WEATHERSTRIP		225 00
10.	1 PC	TAILGATE INNER TRIM BOARD ?		390 00
11.	1 PC	REAR BUMPER / <i>de</i>		995 00
12.	2 PCS	REAR BUMPER SIDE RETAINER ?	48 00	96 00
13.	2 PCS	REAR NUMBER PLATE LAMP / <i>de</i>	98 00	196 00
14.	1 PC	TAILGATE SWITCH		255 00
15.	1 PC	REAR BUMPER REINFORCEMENT ?		685 00
16.	2 PCS	TAILLAMP <i>LH 5 SER. HX an</i>	795 00	1,590 00
17.	1 PC	REAR END PANEL ?		455 00
18.	1 PC	REAR END PANEL GARNISH ?		185 00
19.	1 PC	REAR COMPARTMENT BOARD ?		251 00
20.	2 PCS	REAR FENDER INNER TRIM ?	295 00	590 00
21.	1 PC	FRONT NUMBER PLATE BASE / <i>Gar.</i>		98 00
22.	1 PC	FRONT BUMPER ?		1,152 00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Page 2 / 3

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708403

Date : 16/07/2022

Vehicle Num : SGC 394P

Make/Model : MAZDA 3

Chassis/Eng# :

Accident Date : 16/07/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23	2 PCS	FRONT BUMPER SIDE RETAINER <i>X NN BR</i>	48.00	96.00
24	1 PC	FRONT BUMPER CENTER GRILLE		252.00
25	1 PC	RADIATOR GRILLE <i>cut</i>		545.00
26	1 PC	RADIATOR GRILLE LOGO <i>MC</i>		78.00
27	1 PC	FRONT BUMPER REINFORCEMENT <i>?</i>		785.00
28	1 PC	FRONT BRACE PANEL		58.00
29	1 PC	FRONT SUPPORT PANEL <i>?</i>		585.00
30	1 PC	POWERSTEERING OIL COOLER <i>?</i>		430.00
31	1 PC	AIR CON CONDENSER <i>?</i>		845.00
32	1 PC	RADIATOR <i>?</i>		520.00
33	2 PCS	HEADLAMP <i>?</i>	950.00	1,900.00
34	2 PCS	HEADLAMP LOWER BRACKET <i>?</i>	95.00	190.00
List TotalS\$:				15,885.00
20.00% Discount S\$:				3,177.00
				12,708.00
SPECIAL NETT ITEMS :				
1.	1 PC	TAILGATE GLASS INNER SEAL <i>SMC</i>		80.00
2.	1 PC	TAILGATE GLASS SEALANT		60.00
3.	1 PC	TAILGATE BODY SEALANT <i>X NN</i>		80.00
4.	1 PC	TAILGATE INNER TRIM BOARD CLIPS <i>SMC</i>		40.00
5.	1 PC	REAR BUMPER CLIP		40.00

CONTINUE /

FALCON AIR AUTO SERVICES PTE LTD

Page 3 / 3

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES708403

Date : 16/07/2022
Vehicle Num : SGC 394P
Make/Model : MAZDA 3
Chassis/Eng# :
Accident Date : 16/07/2022
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	1 PC	REVERSE SENSOR		
7.	1 PC	REAR NUMBER PLATE		250.00
8.	1 PC	REAR END PANEL BODY SEALANT		45.00
9.	1 PC	REAR END PANEL GARNISH CLIP		80.00
10.	1 PC	REAR FENDER INNER TRIM CLIP		40.00
11.	1 PC	FRONT NUMBER PLATE		40.00
12.	1 PC	FRONT BUMPER CLIP		45.00
				40.00
Special Nett Total S\$:				840.00
LABOUR :				
TO FOCUS HEADLAMPS.				50.00
TO REMOVE AIR-CON CONDENSOR VUCCUM & RE-GAS				120.00
TO TRANSFER REAR WINDSCREEN GLASS				120.00
TO TRANSFER BOTH TAILGATE PARTS				120.00
TO CHECK WIRING				50.00
TO FIT REVERSE SENSOR IN BUMPER				50.00
TO CONDUCT WATERTEST AT BOOT COMPARTMENT				50.00
TO RUSTPROOF ACCIDENT DAMAGE AREA				250.00
TO REMOVE/REFIX INNER TRIMS ETC TO FACILITATE REPAIRS				250.00
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD				1,200.00
REAR END PANEL AND REPLACEMENT OF PARTS				
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA				1,500.00
Labour Total S\$:				3,760.00

E. & O.E.

Total S\$: 17,308.00

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

68 Days - (7)
45.
After repair photos.
Gino Qian
20/7/22.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "without Prejudice" basis
- No illegal modification allowed
- Supplemental survey on parts surveyed and is subject to final confirmation by Insurance Company

Acknowledged by Repairer

Signature:

Date: