

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

M2053REH104533570

ESTIMATE OF REPAIR

Veh# : SKT8366G

Accident Date : 1/8/22

Location : ubi ave 1 carpark

TP Ergo
Xiao Chen.

Model: TOYOTA COROLLA ALTIS

9/6/2015

3P: GBG2610R (ERGO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Debond</i>	671.20	<i>556</i>	
2	10pcs	Rear bumper clips <i>New</i>		30.00	
3	2pcs	Rear bumper screw clips <i>New</i>		20.00	
4	1pc	Rear bumper enforcement <i>New</i>	251.40	X	
5	1pc	Rear bumper sponge <i>New</i>	142.80	X	
6	1pc	Rear bumper o/s reflector <i>New</i>	95.40	X	
7	1pc	Rear bumper o/s retainer <i>New</i>	162.80	X	
8	2pcs	Rear reverse sensor <i>Damaged</i>		<i>280.00</i>	<i>280.00</i>
9	1pc	Rear end panel <i>New</i>	581.90	X	
10	1pc	Rear end panel inner trim <i>New</i>	253.50	X	
11	4pcs	Rear end panel inner trim clips <i>New</i>		16.00	
12	1pc	Rear o/s tail lamp <i>Cracked</i>	878.20	<i>391</i>	
13	1pc	Rear o/s tail lamp clips <i>New</i>		30.00	
14	1pc	Rear boot cover <i>Dented</i>	874.40	X	
15	1pc	Rear boot cover weatherstrip <i>New</i>	174.40	X	
16	1pc	Rear boot cover emblem <i>New</i>	71.50	X	
17	1pc	Rear boot cover 'COROLLA' emblem <i>New</i>	61.70	X	
18	1pc	Rear boot cover 'ALTIS' emblem <i>New</i>	67.70	X	
19	1pc	Rear o/s boot cover reflector <i>Cracked</i>	710.20	<i>358</i>	
20	2pcs	Rear boot cover o/s & n/s hinges <i>New</i>	164.40	X	
21	1pc	Rear boot cover moulding chrome <i>New</i>	287.10	X	
22	4pcs	Rear boot cover moulding clips <i>New</i>		16.00	
23	1pc	Rear boot cover lock (Upper) <i>Damaged</i>	291.60	X	
Sub Total:			5,740.20	392.00	0.00
25%				0%	10%
After Less %:			4,305.15	392.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	800.00	<i>500</i>	
2		To spray painting.	800.00	<i>400</i>	
3		To remove & replace rear reverse sensor	80.00	<i>50</i>	
4		To check wiring.	80.00	<i>30</i>	
5		To re seal anti rust.	80.00	<i>30</i>	
Sub Total:			1,840.00		
Total:			6,537.15		
After Less 20%:			5,229.72		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed

Chan San Cheon
Director
DipEng, AAE, MIM, MSAE(Aust)

Acknowledged by Repairer

Signature


Date

Signature

Date

Signature

Date



Admin Lg Total: 3485.25
1/8 03/08/22 4/8: 2.71C.
04 pgs