

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22007383/GCY3Q2**Date:** 29/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000213	
Claimant Vehicle No :	SHC2353H	Insured Vehicle No :	SLH1919J	
Date of Loss:	30/07/2022	Nature of Claim:	TP	Claim No: M2204071

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2353H	Engine No:	2ZR2F85892
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU003090067
Reg. Date:	13/12/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,704.43	208.27	1,496.16	87.78
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,620.00	1,100.00	520.00	32.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,335.43	1,319.27	2,016.16	60.45
+ GST 7.00/7.00% (S\$)	233.48	92.35	141.13	60.45
Nett Amount (S\$)	3,568.91	1,411.62	2,157.29	60.45

INSPECTION

Date of Assignment:	02/08/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/08/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Sep 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC2353H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	591.75 FL	*- FL
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	77.00 FL	*- FL
3	1		*FRONT BUMPER PROTECTOR RH	Not Necessary	127.70 FL	*- FL
4	1		*FRONT FENDER RH	Repair	1,111.93 FL	*- FL
5	1		*FRONT FENDER EMBLEM RH	Not Necessary	86.50 FL	*- FL
6	1		*FRONT WHEEL CAP RH	Cut	177.70 FL	*177.70 FL
7	1		*FRONT DOOR COMFORT STCKER	Cut	75.00 FS	*75.00 FS
					Sub Total (\$\$)	2,247.58 252.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	543.15 44.43
					Total Parts (\$\$)	1,704.43 208.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING	New	800.00	750.00
3	CHECK LIGHTING	New	60.00	0.00
4	RESET WHEEL ALIGNMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,620.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >