

Vehicle Damage Assessment Report for [SGY9888G]

Estimate Created: 03/08/2022 10:02 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 12/10/2022 02:07 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	BMW	Model	1-Series
Engine Type			
License Plate Number	SGY9888G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$3311.70 with 3 days for repair

Insurlogic 1 (12/10/2022 02:05)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER PRIMED		1	1019.95	0.00 %	1,019.95
REAR PDC HOLDER SET		1	26.70	0.00 %	26.70
ADHESIVE SET K6		1	53.05	0.00 %	53.05

Parts Subtotal 1,099.70

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
ELECTRICAL CHECK	RnR	168.00	0.00 %	168.00
REPLACE REAR BUMPER AND ATTACHMENT	RnR	850.00	0.00 %	850.00
RNR PDC ASSY	RnR	168.00	0.00 %	168.00
SUNDRIES	RnR	40.00	0.00 %	40.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
REAR BUMPER	Full spray	986.00	0.00 %	986.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,226.00

Paint Labor Subtotal 986.00

Labor Subtotal 2,212.00

Summary

Repair Cost 3,311.70

Discount(0 %) (0.00)

3,311.70

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 3,311.70