

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62642
Date Estimated : 23/07/2022
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chow Sak Yeen
65 Lorong G Telok Kurau
#03-09

Singapore 426323

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGY9888G	WBA1V720205G86542	28/04/2017	116d	39992

DESCRIPTION

Replace rear bumper include remove attachmen etc

Painting rear bumper

To remove and install fuse box at the front section to facilitate repair.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

VALUE

850 1,275.00

286 1,038.00

n^ X 531.00

168 177.00

48 80.00

Total Labour 1: 3,101.00

DESCRIPTION

REAR BUMPER CARRIER X n^

HOLDER CAMERA SYSTEM X n^

HOLDER AERIAL X n^

REAR BUMPER TOWING EYE COVER PRIMED X n^

(S/L) LH PROTECTION FOIL X n^

(S/L) RH PROTECTION FOIL X n^

REAR BUMPER PRIMED (RFC) de

REAR PDC HOLDER SET n^

DECOUPLING RING PDC TORQUE CONVERTE X n^

QTY	PRIC	VALUE
1	424.85	424.85
1	36.50	36.50
1	26.70	26.70
1	39.95	39.95
1	10.90	10.90
1	10.90	10.90
1	1,019.95	1,019.95
1	26.70	26.70
4	5.30	21.20

Total Parts : 1,617.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 157401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62642
Date Estimated : 23/07/2022
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGY9888G	WBA1V720205G86542	28/04/2017	116d	39992

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/08/22 @ 11:20 _____

Surveyor's Name RASUL _____

Surveyor's Tel 90010068 _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,101.00
Parts	:	1,617.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	330.31
Grand Total	:	5,048.96

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 62642**
Date Estimated : **23/07/2022**
Prepared By : **Yap Mee Key**

- ESTIMATE REPAIR FOR -

Chow Sak Yeen
65 Lorong G Telok Kurau
#03-09

Singapore 426323

- ACCOUNT - **219**

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGY9888G	WBA1V720205G865	28/04/2017	116d	39992

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To check electrical wiring system at rear section for proper function	168.00	0.00	168.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# (DG/SL) ADHESIVE SET K6 nec ✓	53.05	1.00	0.00	53.05

SUPPLEMENTARY ITEMS

Total Labour :	168.00
Total Parts :	53.05