Performance Motors

BMW Dealer



India International Insurance Pte Ltd 64 Cecil Street #04-05, IOB Building Singapore 049711

Attn: Motor Claims Dept.

Your ref: CC4/GRB22007385/ga3

Our ref: DS/SGY9888G

20 September 2022

Without Prejudice

ACCIDENT INVOLVING VEHICLES SGY9888G & SLR4118G ON 22/07/2022

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair: \$3,586.32

Loss of Use : \$ 240.00 (\$80 X 3 Days)

Loss of Rental: \$ -

Excess : \$ -

GIA/LTA Search: \$7.45

Others

: \$ -

Total

: \$ 3,833.77

A copy of each of the following supporting documents is enclosed:

- 1. Copy of Tax Invoice & Receipts
- 2. Copy of GIA/LTA search slip
- 3. Copy of GIA Report
- 4. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Cresendo Lagman


Customer Service Manager, Bodyshop

Bernard Wan

Aftersales Manager, Bodyshop

Performance Motors Limited. Sime Darby Performance Centre, 303 Alexandra Road Sime Darby Business Centre, 315 Alexandra Road East Coast Centre, 280 Kampong Arang Road Ubi Service Centre, By-appointments only

Tel: 1800-2255-269 Co Reg No. 197401559W



Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-00200

303. Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190100 (Sale 63190111 (Afte Fax. 64747770 280, Kampong Arang East Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773 315, Alexandra Road Sime Darby Business Singapore 159944 Tel. 63190528 (63190533/530 (Fax. 64796601 (



SERVICE TAX INVOICE

Repair Order No. : **B1 1686528** Page No. : **1 of 2**

Invoice Number: 2569043 / WSB
Date IN : 22/08/2022 Invoice Date : 16/09/0909

Date IN : 22/08/2022 Invoice Date : 16/09/2022

Motor Claim Advisor: Yap Mee Key Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

- CUSTOMER INFORMATION - INVOICE TO - 219

Mr Chow Sak Yeen India Int'L Insurance Pte Ltd

65 Lorong G Telok Kurau 64 Cecil Street #03-09 #04-05 IOB Building Singapore 049711

Singapore 426323

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE SGY9888G WBA1V720205G86542 28/04/2017 116D 42537

LABOUR 1			N
Replace rear bumper include remove attachmen etc			85
Painting rear bumper			98
To check electrical wiring system at rear section for			16
proper function			
To remove oid PDC assembly, replace damaged parts and			16
reconnect to new bumper including conduct check for			
proper function.			
Sundries.			
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.			
DATE OF ACCIDENT :22.07.22. 3RD PARTY CAR :SLR4118G.			
YOUR REF NO :CC4/GRB22007385/			
VEHICLE WAS SURVEYED BY RASUL FROM LKK CONSULTANT			
ON 22.08.22@112OHRS. AUTHORISED BY HSIAO TONG FROM			
LKK VIA EMAIL ON 08.08.22			
PROPOSE LOSS OF USE = \$80X3 THE AMOUNT IS SUBJECTED TO			
INSURANCE COMPANY CONFIRMATION.			
LTA SEARCH FEE = \$7.45.			
	Tota	al Labour 1:	2,2
		Retail	
PARTS	Qty_	Price	
REAR BUMPER PRIMED (RFC)	1	1,019.95	1,0
REAR PDC HOLDER SET	1	26.70	
(DG/SL) ADHESIVE SET K6	1	53.05	
	Tota	al Parts	: 1,09

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190100 (Sale 63190111 (Afte Fax. 64747770 280, Kampong Arang East Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773 315. Alexandra Road Sime Darby Business Sinqapore 159944 Tel. 63190528 (63190533/530 (Fax. 64796601 (



SERVICE TAX INVOICE

Repair Order No. : B1 1686528 Page No. : 2 of 2

Date IN : 22/08/2022 Invoice Number : 2569043 / WSB

Invoice Date : 16/09/2022

Motor Claim Advisor: Yap Mee Key Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

Labour Charges	:	2,172.00	Total Labour & Parts Charges	: S\$	3,351.70
Parts Charges	:	1,099.70	Less Insurance Excess	: S\$	0.00
Lubricant/Misc	:	80.00	Invoice Total Amount Exclude GST	: S\$	3,351.70
			GST @ 7%	: S\$	234.62
			Invoice Total Amount Include GST	: S\$	3,586.32
Computer generated	invoice	e. No signature is required.	Amount Payable Include GST :	S\$	3.586.32



Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.



BMW Dealer

Estimate No.

Performance Motors Limited

: b1 62642

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

Date Estimated : 23/07/2022

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 215, Alexandrs Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



Page No. : 1 of 5

Total Parts

:

1,617.65

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Prepared By : Yap Mee Key	
Chow Sak Yeen Cash 65 Lorong G Telok Kurau Sing #03-09	CCOUNT - 40000 Sales - Service gapore
Singapore 426323	
REGN. NO. CHASSIS NO. REGN. DATE	MODEL MILEAGE
SGY9888G WBA1V720205G86542 28/04/2017	116d 39992
DESCRIPTION	VALUE
Replace rear bumper include remove attachmen etc	QCV 1.275.00
Painting rear bumper	786 1,038.00
To remove and install fuse box at the front section to facilitate repair.	531.00
To remove old PDC assembly, replace damaged parts an reconnect to new bumper including conduct check for proper function.	786 1,038.00 × 531.00 d (68 171.00
Sundries.	¥18 80.00
	Total Labour 1: 3,101.00
DESCRIPTION 7	QTY PRIC VALUE
REAR BUMPER CARRIER .	1 424.85 424.85
HOLDER CAMERA SYSTEM X	1 36.50 36.50
HOLDER AERIAL X	1 26.70 26.70
REAR BUMPER TOWING EYE COVER PRIMED	1 39.95 39.95
(S/L) LH PROTECTION FOIL X (S/L) RH PROTECTION FOIL X	1 10.90 10.90 1 10.90 10.90
REAR BUMPER PRIMED (RFC)	1 1,019.95 1,019.95
REAR PDC HOLDER SET	1 26.70 26.70
	1 20.10 20.10

BMW Dealer

Estimate No.

Date Estimated

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

Sime Darby Performance Centre Singapore 159941 Fax. 64747770

: b1

: 23/07/2022

62642

280. Kampong Arang Road Bast Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad

(AfterSales) (Motorrad)



Page No. : 2 of 5

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Prepared By	: Yap Mee Key			
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGY9888G	WBA1V720205G86542	28/04/2017	116d	39992

Clams OD (Grd Party) Uninsured	osses / Direct Settlement
Date & Time 22/68/22/01/20) ,
Surveyor's Neath RASING	Nutricy sed Yes / No
Surveyor's Tel 90010068	-
Authorised Date	Time PMI Yes / No
Authorised Date RESURVEY PARTS PHOTO BY SURVE	ACK AER IND THE TOP
Surveyor's E-mail	- Palla
No. of Working Days Recommend	3 awys



Labour 1 : 3.101.00 Parts 1,617.65 Labour 2 0.00 Excess 0.00 Total GST @ 7% 330.31

Grand Total

5,048.96

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

25 Jul 2022 / 10:16:52

Receipt Date/Time:

25 Jul 2022 / 10:16:51

Tax Invoice/Receipt

Receipt No.: ITNET-00000-220725-000752

Previous Receipt No.:

Trovidad Hodelpt Ho. :				
S/N Item Description/ Business Transaction Reference No.			gge sembatis	After GST
Result of Insurance Enquiry - SLR4118G As at 22 Jul 2022/18:40:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - SLR4118G				
Enquiry Fee 20220725101319403946		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20220725101349122	Direct Debit: eN (Intern	VETS Debit et Banking)	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Performance Wotors Limited Amember of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING 39798889 & SLR 4189 ON 277722.
I, Chow sak yeen owner of Vehicle Registration No. 367 98886 hereby authorise Performance Motors Limited to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.
I further authorise Performance Motors Limited to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.
I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.
I further confirm that the acceptance by Performance Motors Limited of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.
Signed by:
Name: Chow Sak yeen (Date) 23/7/22 NRIC No.: S 7170418A
In the presence of:
Name: Yap Mee key (Date) 23/7/22 NRIC No.: 62744639P