

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 973901568186Sum Insured: _____ Excess: \$400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 2262B Yr Regn: 12/6/21Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Audi A3 c.c. 1498Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 21378 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAV 2226Y 77A 095134Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 29/7/22 D.O.I. 218/22Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/11 MV-163K
Confirmed final fig \$24,823.88, 9 days with Mr Boo. (Ref 23806.12, 49%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: ODLump Sum / 10%: \$24,823.88

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0643/2022/EQ
DATE : 1-Aug-22
WIP : 35375

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

9 days exclude weekend

15 Nov 22 - Johnny Boo

OWNER'S NAME : MS. NORMALIS ALWI
ADDRESS : BLK 404 WOODLANDS STREET 41
#11-74
SINGAPORE 730404
TELEPHONE : HP +65 97521115
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210059193
VEHICLE NO : **SNA 2262 B**
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFSI
MODEL YEAR : 12/6/2021
ENGINE NO : DFY 268691
CHASSIS NO : WAUZZZGY7MA095134
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jul-22
PLACE OF ACCIDENT : CLEMENTI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 \$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00 \$	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00 \$	1,400.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00 \$	1,200.00
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR.	S/N \$	560.00	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00 \$	2,750.00
SUB-TOTAL LABOUR CHARGES		:	\$ 9,940.00	\$ 6,330.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 6,330.00
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, BOTH FRONT FENDER AND BOTH FRONT DOORS.	\$ 6,000.00	\$ 2,475.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 16,324.00	\$ 9,189.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,677.00	\$	1,341.60
2	FRONT BUMPER FIXING PARTS	1	\$ 290.00		
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 260.00		
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 433.00	\$	346.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 265.00	\$	212.00
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 134.00		
7	FRONT BUMPER SPOILER	1	\$ 326.00	\$	260.40
8	FRONT BUMPER SPOILER COVER TRIM - LH / RH	2	\$ 208.00	\$	165.60
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 342.00	\$	136.40
10	FRONT BUMPER SUPPORT - LH / RH	2	\$ 86.00		
11	RADIATOR GRILLE	1	\$ 932.00	\$	745.60
12	FRONT CLOSING ELEMENT - CENTER	1	\$ 210.00	\$	168.00
13	FRONT LOW & HIGH TONE SIGNAL HORN - LH / RH	2	\$ 314.00		
14	SPRING SHACKLE - LH / RH	8	\$ 247.00		
15	FRONT PARKING AID SENSOR - INNER / OUTER	4	\$ 1,116.00		
16	FRONT PARKING AID SEAL RING	4	\$ 32.00		
17	FRONT BUMPER WIRING SET	1	\$ 252.00		
18	FRONT BUMPER FOAM FILLER PIECE	1	\$ 120.00	\$	95.60
19	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 748.00	\$	598.00
20	FRONT BUMPER SUPPORT - LH / RH	2	\$ 20.00	\$	15.52
SUB TOTAL SPARE PARTS		:	\$ 8,012.00	\$	4,084.72

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 4,084.72
21	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 108.00	
22	FRONT BUMPER TOP COVER	1	\$ 93.00	\$ 74.00
23	CAUTION SIGN STICKER	1	\$ 16.00	\$ 12.40
24	AIR CONDITIONER STICKER	1	\$ 9.00	\$ 6.64
25	FRONT FENDER - LH / RH	2	\$ 2,482.00	
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 64.00	
27	POP RIVET	7	\$ 27.00	
28	FRONT FENDER BRACKET - LH / RH	6	\$ 223.00	
29	FRONT FENDER BRACE - LH / RH	2	\$ 196.00	
30	FRONT FENDER ATTACHMENT PARTS	1	\$ 121.00	
31	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 366.00	
32	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 44.00	
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 125.00	
34	BONNET	1	\$ 3,271.00	\$ 2,616.80
35	LID HINGE - LH / RH	2	\$ 136.00	
36	BONNET ATTACHMENT PARTS	1	\$ 256.00	
37	BONNET IMPACT PROTECTION - CENTER	1	\$ 30.00	\$ 23.60
38	FRONT FENDER COVER - LH / RH	2	\$ 92.00	
39	BONNET STRIKER - LH / RH	2	\$ 246.00	
40	BONNET RELEASE ELEMENT	1	\$ 65.00	
SUB TOTAL SPARE PARTS		:	\$ 7,970.00	\$ 6,818.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	6,818.16
41	BONNET RELEASE LEVER	1	\$ 15.00		
42	BONNET LID LOCK - LH / RH	2	\$ 455.00		
43	BONNET BOWDEN CABLE - CENTER	1	\$ 61.00		
44	BONNET BOWDEN CABLE COVER	1	\$ 11.00		
45	BONNET LID LOCK CABLE - RH	1	\$ 82.00		
46	FRONT PLENUM CHAMBER COVER	1	\$ 177.00		
47	BONNET GAS FILLED STRUT	1	\$ 110.00		
48	FRONT HEADLIGHT - LH / RH	2	\$ 8,168.00	\$	6,534.40
49	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 422.00		
50	LIFT CYLINDER HOSE	1	\$ 108.00		
51	WASH WATER RESERVOIR	1	\$ 179.00	\$	143.20
52	LOCK CARRIER MOUNTING	1	\$ 990.00	\$	792.00
53	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	\$	16.32
54	A/C CONDENSER	1	\$ 569.00	\$	454.80
55	RADIATOR FAN RING	1	\$ 1,061.00		
56	COOLANT ADDITIONAL RADIATOR	1	\$ 959.00		
57	RADIATOR FAN RING	1	\$ 1,339.00		
58	READY-MIX COOLANT	6	\$ 282.00	\$	237.12
59	RADIATOR AIR GUIDE - LH / RH	2	\$ 84.00	\$	65.76
60	RADIATOR FRONT SEAL - RH	1	\$ 14.00	\$	11.12
SUB TOTAL SPARE PARTS		:	\$ 15,107.00	\$	15,072.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	15,072.88
61	RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 59.00	\$	46.64
62	FRONT INTAKE AIR DUCT COVER	1	\$ 30.00	\$	23.84
63	FRONT INTAKE AIR GUIDE	3	\$ 130.00	\$	74.56
64	ALT INTAKE WATER DRAINAGE HOSE	1	\$ 37.00		
65	AIR FILTER	1	\$ 310.00	\$	269.20
66	INTAKE AIR GUIDE FLAP	1	\$ 27.00	\$	21.36
67	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
68	Added parts		\$ 64.00	\$	51.20
69	SUNDRIES		\$ 500.00	\$	15.20
TOTAL SPARE PARTS		:	\$ 32,306.00	\$	15,634.88
TOTAL LABOUR CHARGES		:	\$ 16,324.00	\$	9,189.00
GRAND TOTAL		:	\$ 48,630.00	\$	24,823.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-05/10/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0643/2022/EQ 17-Aug-22 CHANG 1 of 1 SNA 2262 B AUDI A3 SPORTBACK 1.5 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	OUTER TEMPERATURE SENSOR 1	\$ 64.00	\$	51.20
GRAND TOTAL		\$ 64.00	\$	51.20

BR ✓

For Premium Automobiles Pte Ltd

 Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0643/2022/EQ
DATE : 1-Aug-22
WIP : 35375

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. NORMALIS ALWI
ADDRESS : BLK 404 WOODLANDS STREET 41
#11-74
SINGAPORE 730404
TELEPHONE : HP +65 97521115
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210059193
VEHICLE NO : SNA 2262 B
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFSI
MODEL YEAR : 12/6/2021
ENGINE NO : DFY 268691
CHASSIS NO : WAUZZZGY7MA095134
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jul-22
PLACE OF ACCIDENT : CLEMENTI ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <i>25 x 2</i>	S/N \$ 700.00 <i>500</i>	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00 /	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR.	S/N \$ 560.00 X	
<i>Rip - 1</i> 6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 <i>2750</i>	
SUB-TOTAL LABOUR CHARGES		: \$ <u>9,940.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, BOTH FRONT FENDER AND BOTH FRONT DOORS. ¹ ₂ ? ✓ 275	\$ 6,000.00 SSD x 4	2750 2475
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 16,324.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / BR	1	\$ 1,677.00 /	1344.60	
2	FRONT BUMPER FIXING PARTS X X m	1	\$ 290.00		
3	FRONT BUMPER CLOSING ELEMENT - LH / RH X X m	2	\$ 260.00		
4	FRONT BUMPER GRILLE - LOWER CENTRE / BR	1	\$ 433.00 /	346.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	1	\$ 13R 265.00 /	212.00	
6	FRONT BUMPER AIR GUIDE - LH / RH X X m	2	\$ 134.00		
7	FRONT BUMPER SPOILER X CRU	1	\$ 326.00 /	260.40	
8	FRONT BUMPER SPOILER COVER TRIM - LH / RH - CRU 1.27	\$	208.00 /	165.60	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH 1 (LH) 21	\$ BR	342.00 136.40 / 136.40		
10	FRONT BUMPER SUPPORT - LH / RH X X m	2	\$ 86.00		
11	RADIATOR GRILLE / BR	1	\$ 932.00 /	745.60	
12	FRONT CLOSING ELEMENT - CENTER / BR	1	\$ 210.00 /	168.00	
13	FRONT LOW & HIGH TONE SIGNAL HORN - LH / RH X X m	2	\$ 314.00		
14	SPRING SHACKLE - LH / RH X X m	8	\$ 247.00		
15	FRONT PARKING AID SENSOR - INNER / OUTER X X m	4	\$ 1,116.00		
16	FRONT PARKING AID SEAL RING X X m	4	\$ 32.00		
17	FRONT BUMPER WIRING SET ? X m	1	\$ 252.00		
18	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$ 120.00 /	95.60	
19	FRONT BUMPER REINFORCEMENT BEAM / DD	1	\$ 748.00 /	598.00	
20	FRONT BUMPER SUPPORT - LH / RH X / MC	2	\$ 20.00 /	15.52	
SUB TOTAL SPARE PARTS		:	\$ 8,012.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BUMPER GUIDE SECTION - LH / RH	2	S	108.00	
22	FRONT BUMPER TOP COVER	1	S	93.00	74.00
23	CAUTION SIGN STICKER	1	S	16.00	12.40
24	AIR CONDITIONER STICKER	1	S	9.00	6.64
25	FRONT FENDER - LH / RH	2	S	2,482.00	
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	S	64.00	
27	POP RIVET	7	S	27.00	
28	FRONT FENDER BRACKET - LH / RH	6	S	223.00	
29	FRONT FENDER BRACE - LH / RH	2	S	196.00	
30	FRONT FENDER ATTACHMENT PARTS	1	S	121.00	
31	FRONT WHEEL HOUSING LINER - LH / RH	2	S	366.00	
32	FRONT FENDER CLOSING ELEMENT - LH / RH	2	S	44.00	
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	S	125.00	
34	BONNET	1	S	3,271.00	2616.80
35	LID HINGE - LH / RH	2	S	136.00	
36	BONNET ATTACHMENT PARTS	1	S	256.00	
37	BONNET IMPACT PROTECTION - CENTER	1	S	30.00	23.60
38	FRONT FENDER COVER - LH / RH	2	S	92.00	
39	BONNET STRIKER - LH / RH	2	S	246.00	
40	BONNET RELEASE ELEMENT	1	S	65.00	
SUB TOTAL SPARE PARTS		:	\$	7,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BONNET RELEASE LEVER <i>X nn</i>	1	S	15.00	
42	BONNET LID LOCK - LH / RH <i>X nn</i>	2	S	455.00	
43	BONNET BOWDEN CABLE - CENTER <i>X nn</i>	1	S	61.00	
44	BONNET BOWDEN CABLE COVER <i>X nn</i>	1	S	11.00	
45	BONNET LID LOCK CABLE - RH <i>X nn</i>	1	S	82.00	
46	FRONT PLENUM CHAMBER COVER <i>X nn</i>	1	S	177.00	
47	BONNET GAS FILLED STRUT <i>X nn</i>	1	S	110.00	
48	FRONT HEADLIGHT - LH / RH <i>BR</i>	2	S	8,168.00	6534.40
49	HEADLIGHT LIFT CYLINDER - LH / RH <i>X nn</i>	2	S	422.00	
50	LIFT CYLINDER HOSE <i>X nn</i>	1	S	108.00	
51	WASH WATER RESERVOIR <i>CR4</i>	1	S	179.00	143.20
52	LOCK CARRIER MOUNTING <i>BR</i>	1	S	990.00	792.00
53	OUTSIDE TEMPERATURE SENSOR BRACKET <i>X</i>	1	S <i>ACC</i>	21.00	16.32
54	A/C CONDENSER <i>X nn</i>	1	S <i>BT</i>	569.00	454.80
55	RADIATOR FAN RING <i>X nn</i>	1	S	1,061.00	
56	COOLANT ADDITIONAL RADIATOR <i>X nn</i>	1	S	959.00	
57	RADIATOR FAN RING <i>X nn</i>	1	S	1,339.00	
58	READY-MIX COOLANT <i>ACC</i>	6	S	282.00	237.12
59	RADIATOR AIR GUIDE - LH / RH <i>X</i>	2	S <i>BR</i>	84.00	65.76
60	RADIATOR FRONT SEAL - RH <i>X</i>	1	S <i>BR</i>	14.00	11.12
SUB TOTAL SPARE PARTS			: \$ 15,107.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	RADIATOR AIR GUIDE - LOWER CENTRE <i>BR</i>	1	\$	59.00	<i>46.64</i>
62	FRONT INTAKE AIR DUCT COVER <i>BR</i>	1	\$	30.00	<i>23.84</i>
63	FRONT INTAKE AIR GUIDE <i>BR</i>	<i>2.5</i>	\$	130.00	<i>74.56 / 74.56</i>
64	ALT INTAKE WATER DRAINAGE HOSE <i>?</i>	1	\$	37.00	
65	AIR FILTER <i>A</i>	1	\$ <i>BR</i>	310.00	<i>269.20</i>
66	INTAKE AIR GUIDE FLAP <i>A</i>	1	\$ <i>BR</i>	27.00	<i>21.36</i>
67	FRONT NO PLATE <i>ms</i>	S/N	\$	60.00	<i>60.00</i>
68	SUNDRIES <i>hpc</i>		\$	500.00	<i>15.20 / 15.20</i>
TOTAL SPARE PARTS		:	\$	32,242.00	
TOTAL LABOUR CHARGES		:	\$	16,324.00	
GRAND TOTAL		:	\$	48,566.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
218/22, 3-22P

3D-41 A-
EXC. - 7
P/P

4 PL by
9 dy

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary cost(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT