

Not Not hatched  
Purong B&paint

81434.60

AAD2208-

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9918C**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

02 AUG 2022

**SHD9918C**

JTDKB3FU403093280

200303878K

TOYOTA

PRIUS GEN 4

01/08/2022

**SMH4525E/AUTO GEN**

30/12/2020

|                                       |    | LIST     |   |
|---------------------------------------|----|----------|---|
| PART                                  |    |          |   |
| 1 COVER, REAR BUMPER                  | \$ | 485.60   | ✓ |
| 1 REINFORCEMENT SUB-ASSY, REAR BUMPER | \$ | 332.70   | ✓ |
| 1 GUARD, REAR BUMPER, CENTER          | \$ | 374.50   | ✓ |
| 1 SEAL, REAR BUMPER SIDE, LH          | \$ | 118.30   | X |
| 1 SEAL, REAR BUMPER SIDE, RH          | \$ | 118.30   | X |
| 1 RETAINER, REAR BUMPER SIDE, RH      | \$ | 132.60   | X |
| 1 RETAINER, REAR BUMPER SIDE, LH      | \$ | 132.60   | X |
| 1 COVER, REAR BUMPER, LOWER           | \$ | 22.00    | X |
| 1 COVER, DECK TRIM, REAR              | \$ | 126.70   | ✓ |
| 1 PANEL SUB-ASSY, BODY LOWER BACK     | \$ | 651.00   | X |
| 1 COVER, FLOOR UNDER, NO.2 (RH)       | \$ | 241.90   | X |
| 1 COVER, FLOOR UNDER, NO.1 (LH)       | \$ | 175.10   | X |
| 1 COVER, REAR FLOOR (CTR)             | \$ | 229.90   | X |
| TOTAL \$                              |    | 3,141.20 |   |
| 25% \$                                |    | 785.30   |   |
| \$                                    |    | 2,355.90 |   |

**Special Nett**

|                             |    |        |   |
|-----------------------------|----|--------|---|
| 1 REAR BUMPER SIDE CLIP     | \$ | 60.00  | ✓ |
| 1SET PARKING AID            | \$ | 700.00 | X |
| 1SET REAR BUMPER CLIP       | \$ | 85.00  | X |
| 1 REAR BUMPER RETAINER CLIP | \$ | 75.00  | X |
| TOTAL \$                    |    | 920.00 |   |

**TOTAL PARTS \$ 3,275.90**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9918C**

AAD2208-

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,800.00 *2000*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ *nn* 380.00 X

Putty And Spray Painting Of The Affected Portion. \$ 1,600.00 *2200*

To reinstall rear bumper parking sensor. \$ 170.00 *500*

To transfer of tire, rim and on wheel balancing. \$ NN 170.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *100*

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test. \$ *nn* 170.00 X

**TOTAL \$ 5,300.00****Over All Total \$ 8,575.90****(PART-BY-PART) Repair Days***20 Days**2 days*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: