

ASS. REC. BY:

REF: AG2/ 220073911kv

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S140 9918C Yr Regn: 12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour mp. white 1Rw A/C: Insured / Std / NI / NA

Sp. Reading 170565 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU403093280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Sza: F: 175/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wadi

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 1/18/22 D.O.I. 2/8/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got B1

81434.60

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: \_\_\_\_\_

1)

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:  : Site Insp (\$ )

Transportation

: Interview (\$ )

S - RS - SI

: Tech Invs (\$ )

Fixes

: Weekend (\$ )

Others

Report Format :

Lump Sum / I.B.I: (\$ )

TOTAL

Not Authoised  
Purway B&Paint

81434.60

AAD2208-

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9918C**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**02 AUG 2022**

**SHD9918C**

JTDKB3FU403093280

200303878K

TOYOTA

PRIUS GEN 4

01/08/2022

**SMH4525E/AUTO GEN**

30/12/2020

	<b>PART</b>
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, LH
1	COVER, REAR BUMPER, LOWER
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	COVER, FLOOR UNDER, NO.2 (RH)
1	COVER, FLOOR UNDER, NO.1 (LH)
1	COVER, REAR FLOOR (CTR)

	<b>LIST</b>	
\$	An	485.60 ✓
\$	Bz	332.70 ✓
\$	Bz	374.50 ✓
\$	Sn	118.30 X
\$	Sn	118.30 X
\$	Sn	132.60 X
\$	Sn	132.60 X
\$	Sn	22.00 X
\$	Sn	126.70 X
\$	K	651.00 X
\$	Sn	241.90 X
\$	Sn	175.10 X
\$	Sn	229.90 X
<b>TOTAL</b>	<b>\$</b>	<b>3,141.20</b>
<b>25%</b>	<b>\$</b>	<b>785.30</b>
	<b>\$</b>	<b>2,355.90</b>

**Special Nett**

1	REAR BUMPER SIDE CLIP
1SET	PARKING AID
1SET	REAR BUMPER CLIP
1	REAR BUMPER RETAINER CLIP

\$	Mn	60.00 ✓
\$	Sn	700.00 X
\$	nn	85.00 X
\$	nn	75.00 X
<b>TOTAL</b>	<b>\$</b>	<b>920.00</b>

**TOTAL PARTS \$ 3,275.90**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 240.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9918C**

**AAD2208-**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>200l</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>220l</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50l</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>10l</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>5,300.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>8,575.90</b>	

**(PART-BY-PART) Repair Days**

*20 Days*

*2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	02/08/2022 12:04 (SGT)
Reported by	Driver
Date of Accident	01/08/2022 20:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BRADDELL ROAD TOWARDS TOA PAYOH BELOW SERANGOON VADUCT
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9918C
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	Claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	5DR HATCHBACK (AUTO)
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767


## INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

## DRIVER

Name of Driver	LEOW CHEN HEE
NRIC No	SXXXX057C
Date Of Birth	10/06/1957

ACCIDENT DIAGRAM



veh A: SHD9918C

veh B: SMH4525E

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

VERIFIED BY AJAX MARS (ARC)  
REPORTING OFFICER  
ANG QI HAO, VICTOR

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: