

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6481 1916

E-Mail: csongauto.claims@yahoo.com.sg

To: MS FIRST CAPITAL
Att: Motor Claims Dept

ACCIDENT INVOLVING SMB88H [YOUR INSURED] & SLD7227D [YOUR CLIENT] ON 29/07/2022.

- sg Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
- Work done by you/your client is resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

ESTIMATED REPAIR COSTS FOR SLD7227D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET HH	\$ 2,348.55	X
1PC	BONNET INSULATOR HH	\$ 248.36	X
1PC	BONNET SEAL HH	\$ 101.50	X
1PC	HEAD LAMP LH <i>mostly broken</i>	2302.00 \$ 2,762.90	✓
1PC	HEAD LAMP LOWER BRACKET LH <i>broken</i>	289.60 \$ 369.15	✓
1PC	HEAD LAMP ECU LH HH	\$ 769.40	X
1PC	HEAD LAMP WIRE HARNESS HH	\$ 1,201.34	X
1PC	FRONT BUMPER HEAD LAMP NOZZLE CAP LH HH	\$ 103.15	X
1PC	FRONT BUMPER SIDE GRILLE LH HH	\$ 281.69	X
1PC	FRONT BUMPER SENSOR @ \$361.16 EACH HH	\$ 1,444.64	X
1PC	FRONT BUMPER SENSOR HOLDER @ \$65.39 EACH HH	\$ 261.56	X
1PC	FRONT BUMPER SENSOR WIRE HARNESS HH	\$ 930.00	X
1PC	FRONT BUMPER UNDER COVER HH	\$ 228.95	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$295.14 EACH HH	\$ 590.28	X
1PC	FRONT BUMPER SPONGE HH	\$ 395.60	X
1PC	FRONT REINFORCEMENT BAR HH	\$ 1,065.12	X
1PC	FRONT SUPPORT PANEL HH	\$ 3,180.00	X
1PC	FRONT FENDER LH <i>tear</i>	\$ 1,288.16	X
1PC	FRONT FENDER INNER SHIELD LH HH	\$ 195.44	X
1PC	FRONT FENDER LAMP LH HH	\$ 480.90	X
1PC	FRONT FENDER LAMP CHROME GARNISH LH HH	\$ 316.70	X
1PC	FRONT WHEEL HOUSING LH HH	\$ 3,987.15	X
1PC	FRONT WHEEL BEARING & HUB ASSY LH <i>Dist</i>	552.45 \$ 656.15	✓
1PC	FRONT KNUCKLE ARM LH <i>dist</i>	679.50 \$ 966.19	✓
1PC	FRONT LOWER ARM LH <i>dist</i>	425.00 \$ 548.15	✓
1PC	FRONT THRUST ARM LH HH	\$ 470.17	X
1PC	FRONT ABSORBER LH <i>dist</i>	522.30 \$ 698.95	✓
1PC	FRONT UPPER ARM LH HH	\$ 606.50	X
1PC	FRONT CONTROL ARM LH HH	\$ 520.17	X
1PC	FRONT STABILIZER LINK LH HH	\$ 231.20	X

IPC	FRONT STABILIZER BAR HH	\$ 574.30	X
IPC	FRONT TIE ROD LH HH	\$ 319.00	X
IPC	FRONT TIE ROD END LH HH	\$ 215.24	X
IPC	STEERING RACK & PINION ASSY HH	\$ 6,443.35	X

PARTS SUM: \$ 34,799.91
 PARTS LESS 5%: \$ 1,740.00
 PARTS TOTAL: \$ 33,059.91

4,770.85
 10% 4,293.76

LABOUR & SPECIAL NETT ITEMS

- * TO SUPPLY HEAD LAMP STICKER HH \$ 400.00 X
- * TO SUPPLY IPC SPORT RIM cut 800.00 \$ 2,800.00 ✓
- * TO SUPPLY IPC TYRE cut 50% depre depreciation 400/- \$ 600.00 200/-
- * TO SUPPLY FRONT BUMPER (M5 BODYKIT) cut/monthly cost 1700.00 \$ 3,000.00 ✓
- * TO SUPPLY FRONT BUMPER LOWER LID (M5 BODYKIT) SV2 \$ 2,000.00 X
- * TO SUPPLY FRONT BUMPER SIDE GRILLE HH \$ 1,000.00 X
- * TO SUPPLY FRONT BUMPER CLIPS Nec \$ 50.00 20/-
- * TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HH 2720.00 \$ 50.00 X
- * TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIAE REPAIRS \$ 300.00 HH
- * TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS \$ 3,000.00 600/-
- * TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS \$ 3,000.00 500/-
- * TO TUFF COAT DAMAGED AREAS 1520.00 \$ 300.00 HH
- * TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS \$ 400.00 180/-
- * TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 120.00 60/-
- * TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS \$ 200.00 30/-
- * TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS \$ 300.00 120/-

LABOUR & S/N TOTAL: \$ 17,520.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 50,579.91

03/08/2022 @ 1500

Not Avail

2 hrs 5 dgs.

[Handwritten signature]

8,533.76
 4/5 6,800/-