

Not Notarised  
 Preliminary B4 print

4154.28

AAD2208-

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHB9967X**

Vehicle No.:		<b>SHB9967X</b>
Chassis No.:	<b>02 AUG 2022</b>	JTDKB3FU603092325
Co UEN:		200303878K
Vehicle Make:		TOYOTA
Vehicle Model:		PRIUS GEN 4
Date of Accident :		29/07/2022
Third Party Insurer :		<b>SJY5988S/CHINA</b>
Date of Registration :		30/06/2021

PART	LIST		
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$	<i>By</i> 1,300.70	✓
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$	<i>n</i> 110.60	X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$	<i>n</i> 97.50	X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$	<i>na</i> 13.30	—
1 TAPE, BLACK OUT, NO.2 FRT LH	\$	<i>na</i> 43.50	—
1 TAPE, BLACK OUT, NO.3 FRT LH	\$	<i>na</i> 26.30	—
1 PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>By</i> 1,294.90	✓
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	<i>sn</i> 193.50	X
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	<i>sn</i> 97.40	X
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	<i>sn</i> 293.00	X
1 HINGE ASSY, REAR DOOR, LOWER LH	\$	<i>n</i> 87.10	X
1 HINGE ASSY, REAR DOOR, UPPER LH	\$	<i>n</i> 98.90	X
1 TAPE, BLACK OUT, NO.1 REAR LH	\$	<i>na</i> 21.90	✓
1 TAPE, BLACK OUT, NO.2 REAR LH	\$	<i>na</i> 34.90	✓
1 TAPE, BLACK OUT, NO.3 REAR LH	\$	<i>na</i> 15.40	✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	<i>sn</i> 926.00	X
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	<i>sn</i> 206.70	X
1 PANEL SUB-ASSY, QUARTER, LH	\$	<i>n</i> 871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$	<i>sn</i> 139.80	X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	<i>cm</i> 594.80	✓
1 RIM	\$	<i>sn</i> 1,900.10	X
<b>TOTAL</b>	<b>\$</b>	<b>6,775.90</b>	
<b>25%</b>	<b>\$</b>	<b>1,693.98</b>	
	<b>\$</b>	<b>5,081.93</b>	

1982

AAD2208-

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9967X**

**Special Nett**

1 TYRE	\$	Sm 350.00 X
1 REAR BUMPER CLIP	\$	nn 65.00 X
1 FENDER CLIP	\$	nn 130.00 X
1 FENDER LINER CLIP	\$	nn 65.00 X
1SET DOOR TRIM CLIP	\$	nn 70.00 X
1SET DOOR WEATHERSTRIP CLIP	\$	nn 130.00 X
1 DOOR STICKER TEL NO.	\$	100.00 60sm
1SET CLIP, ROCKER PANEL MOULDING	\$	nn 65.00 ✓
<b>TOTAL</b>	<b>\$</b>	<b>975.00</b>

**TOTAL PARTS \$ 6,056.93**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00 601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00 5001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00 8001
To reinstall rear bumper parking sensor.	\$	nn 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201

**Trans-cab Auto Services Pte Ltd**

AAD2208-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9967X**

To check steering geometry and computer wheel alignment \$ ~~220.00~~ X

To remove and refit of rear fender fittings, attachment and \$ ~~170.00~~ X

**TOTAL \$ 5,100.00**

**Over All Total \$ 11,156.93**

**(PART-BY-PART) Repair Days**

~~20 days~~

4 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: