

Vehicle No : SMB1518C

Policy No :

D-22099124MFBP

Claim No :

Our Ref No:

ADJUSTMENT ON REPAIRS COST AND REPLACEMENT OF PARTS

Qty	Descriptions of parts	Condition	Repairers Est (\$)	Recommendation Revised (\$)
1	Signal Lamp Led	Damaged	\$1,274.10	\$1,274.10
2	Stop Lamp Led	Damaged	\$2,283.40	\$2,283.40
1	Cover Rear Tail Lamp RH	Repair	\$974.70	--
			<u>\$4,532.20</u>	<u>\$3,557.50</u>
Less 10%			\$453.22	\$355.75
			<u>\$4,078.98</u>	<u>\$3,201.75</u>

Special Nett Items

Qty	Descriptions	Condition	Repairers Est (\$)	Recommendation Revised (\$)
			<u>\$4,078.98</u>	<u>\$3,201.75</u>
			Less 20%	\$815.80
			<u>\$3,263.18</u>	<u>\$2,561.40</u>

Labour Charges & Misc

To remove & install all above items and repair others damaged affected areas
To provide labour and material to putty and respray above repair items

Repairers Est (\$)	Recommendation Revised (\$)
\$795.00	265 \$530.00
\$708.00	\$538.00
<u>\$1,503.00</u>	<u>\$1,068.00</u>

Grand Total :	<u>\$4,766.18</u>	<u>\$3,629.40</u>
Lump Sum		\$3,650.00

ADJUSTMENT / RECOMMENDATIONS

No of day repair : 1 day

We have thoroughly inspected each and every item on the estimate against the physical damage found the vehicle we have listed the breakdown of our findings and our recommendation as per assessment above .

Automotive Services Pte Ltd
Low Thian Seng
Fax No : 63687421
Tel No : 68662796
E-mail : thianseng@smrt.com.sg

2561.40
803.00

3364.40

L/S-\$3,350/1 DAY