

Automobile Inspection Report**1) REFERENCE**

Policy No : D-22099124MFBP Date Of Accident : 30/05/2022 2100pm
 Claims No : _____ Date Of Inspection : 23/06/2022 0900am
 Assigned by : Catherine 22/06/22 1100am Date Of Re-inspection : A/F repair photo 23/06/22 0900am
 Case Ref No : BUS/05/22/7032 Inspected By : Low Thian Seng
Car

2) VEHICLE PARTICULARS

Veh Reg No : SMB1518C Engine No : 50338380023841
 Make / Model : Man Bus NL320F Chassis No. : WMAA22ZZ8E7002303
 Year : 20/11/2014 Mileage : 616466
 Colour : Multicolor

3) CONDITION OF VEHICLE (Static Check)

Foot brake : Serviceable Handbrake : Serviceable
 Steering : Serviceable Paintwork : Good

4) TYRE CONDITION

	<u>Size</u>	<u>Make</u>	<u>Balance</u>
Frt Right	<u>275 70R 22.5</u>	<u>Firenza</u>	<u>14mm</u>
Frt Left	<u>275 70R 22.5</u>	<u>Firenza</u>	<u>14mm</u>
Rear Right	<u>275 70R 22.5</u>	<u>Firenza</u>	<u>14mm</u>
Rear Left	<u>275 70R 22.5</u>	<u>Firenza</u>	<u>14mm</u>

5) DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear right body was scratched and rear right signal cover was broken.
For details, please refer to photographs and assessment for repairs.

6) INSPECTION

SURVEY HELD AT : 60, Woodlands Ind Pk E4
 PHOTOGRAPH TAKEN : 26 INSPECTION ON : 23/06/2022 0900am

REMARKS : (SUBJECT TO POLICY CONDITION)
 WITHOUT PREJUDICE

ESTIMATED NORMAL PERIOD FOR REPAIRS : 1 day
 IN ACCORDANCE TO YOUR INSTRUCTION , WE HAVE NOT AUTHORISED REPAIRS .

This estimate covers visible damages only . Should there be any discrepancy or unseen items in this survey , kindly notify the company within (7) days from the date hereof . Otherwise this estimate / acceptance shall be treated as valid .

* Remarks : QX2310P

Lump Sum Repair / Paper Survey

Vehicle No : SMB1518C

Policy No :

D-22099124MFBP

Claim No :

Our Ref No:

ADJUSTMENT ON REPAIRS COST AND REPLACEMENT OF PARTS

Qty	Descriptions of parts	Condition	Repairers Est (\$)	Recommendation Revised (\$)
1	Signal Lamp Led	Damaged	\$1,274.10	\$1,274.10
2	Stop Lamp Led	Damaged	\$2,283.40	\$2,283.40
1	Cover Rear Tail Lamp RH	Repair	\$974.70	--
			\$4,532.20	\$3,557.50
Less 10%			\$453.22	\$355.75
			\$4,078.98	\$3,201.75

Special Nett Items

Qty	Descriptions	Condition	Repairers Est (\$)	Recommendation Revised (\$)
			\$4,078.98	\$3,201.75
Less 20%			\$815.80	\$640.35
			\$3,263.18	\$2,561.40

Labour Charges & Misc

	Repairers Est (\$)	Recommendation Revised (\$)
To remove & install all above items and repair others damaged affected areas	\$795.00	\$530.00
To provide labour and material to putty and respray above repair items	\$708.00	\$538.00
	\$1,503.00	\$1,068.00

Grand Total :	\$4,766.18	\$3,629.40
Lump Sum		\$3,650.00

ADJUSTMENT / RECOMMENDATIONS

No of day repair : 1 day

We have thoroughly inspected each and every item on the estimate against the physical damage found the vehicle we have listed the breakdown of our findings and our recommendation as per assessment above .

Automotive Services Pte Ltd
 Low Thian Seng
 Fax No : 63687421
 Tel No : 68662796
 E-mail : thianseng@smrt.com.sg






STROES AU
* SERVICE
SPELID









STRIDES AUTO
NE S
3PT








STRIDES AUTOMOTIVE
PTD





A circular blue stamp with the text 'AUTOMOTIVE SERVICES' and 'S. FELD' around the perimeter.