



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details				Account No.		Customer Details			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept <i>67418434</i> <i>Lick Yan</i> <i>Survey on 4/8/22</i> <i>1030hr</i>				S1000010 / ICNI3		Mr Lim Keng Goy (Lin Qinyi)			
				Document No.		470 Siglap Road			
				0		#04-37			
				Document Date		Singapore 454943			
				28/07/2022		Mobile: 98582826			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AGL25R	AWTGZ L3	08/10/2018	SMF8988L	0	21379	64OD/SMF8988L/270722		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTJBAMCA802060157		8ARW920833	60	Wally Tan G H	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount			
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPG21013802 ACC DATE:27.07.2022 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 / 80.00			
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50			
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50			
4	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT, R/H AND L/H HEADLAMP PANEL AND FIT NEW PARTS. <i>866</i> <i>(Take photo if need repair front panel)</i>				2598.00			
5	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>742</i>				1484.00			
6	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50			
7	1	L81145-48D30 UNIT, HEADLAMP <i>7 x nn</i>	1.00	7900.10		7900.10			
8	2	L81185-48D30 UNIT, HEADLAMP <i>1 x nn</i>	1.00	7900.10		7900.10			
9	3	L53121-48130 MOULDING, RADIATOR <i>(change upper) - BR</i>	1.00	642.80		642.80			
For & on behalf of			Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd									
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Customer Copy

chcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details				
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept			S1000010 / ICN13		Mr Lim Keng Goy (Lin Qinyi)				
			Document No. 0		470 Siglap Road #04-37 Singapore 454943				
			Document Date 28/07/2022		Mobile: 98582826				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AGL25R	AWTGZ L3	08/10/2018	SMF8988L	0	21379	64OD/SMF8988L/270722		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTJBAMCA802060157		8ARW920833	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
10	4	L53122-48050	MOULDING, RADIATOR <i>BR (che 12)</i>			1.00	1051.80		1051.80
11	5	L53395-48080	SEAL, HOOD TO <i>BR</i>			1.00	55.40		55.40
12	6	L53111-48330	GRILLE, RADIATOR <i>BR (10)</i>			1.00	1433.40		1433.40
13	7	L53112-48320	GRILLE, RADIATOR, <i>BR</i>			1.00	354.30		354.30
14	8	T90975-02125	EMBLEM, SYMBOL <i>X nn</i>			1.00	516.60		516.60
15	9	L89348-48040	RETAINER, ULTRASONIC <i>BR</i>			1.00	20.90		20.90
16	0	L89348-48050	RETAINER, ULTRASONIC <i>BR</i>			1.00	20.90		20.90
17	1	L52535-48050	RETAINER, FR BUMPER <i>BR</i>			1.00	135.70		135.70
18	2	L52536-48040	RETAINER, FR BUMPER <i>BR</i>			1.00	135.70		135.70
19	3	L52021-48051	REINFORCEMENT <i>X nn</i>			1.00	802.50		802.50
20	4	L52611-48181	ABSORBER, FR BUMPER <i>BR</i>			1.00	120.90		120.90
21	5	L52618-48021	ABSORBER, FR BUMPER, <i>X nn</i>			1.00	199.70		199.70
22	6	L52119-4D938	COVER, FR BUMPER <i>BR</i>			1.00	1223.90		1223.90
23	7	L52125-48091	BRACKET, FOG LAMP <i>X nn</i>			1.00	169.20		169.20
24	8	L52126-48091	BRACKET, FOG LAMP <i>X nn</i>			1.00	173.80		173.80
25	9	L52127-48140	COVER, FR BUMPER <i>X nn</i>			1.00	52.10		52.10
26	0	L52128-48110	COVER, FR BUMPER <i>BR</i>			1.00	52.10		52.10
27	1	L81481-48220	COVER, FOG LAMP, RH <i>X nn</i>			1.00	134.40		134.40
28	2	L81482-48200	COVER, FOG LAMP, LH <i>X nn</i>			1.00	134.40		134.40
29	3	L53141-48090	GARNISH, RADIATOR <i>X nn</i>			1.00	81.90		81.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Customer Copy

schcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-850000-9

No 2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Lim Keng Goy (Lin Qinyi)	
		Document No. 0	470 Siglap Road #04-37 Singapore 454943	
		Document Date 28/07/2022	Mobile: 98582826	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGL25R	AWTGZ L3	08/10/2018	SMF8988L	0	21379	64OD/SMF8988L/270722

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTJBAMCA802060157	8ARW920833	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	4	L53142-48040 GARNISH, RADIATOR <i>x</i> <i>CRV (chrome)</i>	1.00	81.90		81.90 ✓
31	5	L53285-48030 COVER, FR BUMPER ARM <i>x</i> <i>nn</i>	1.00	108.40		108.40 ✓
32	6	L53286-48020 COVER, FR BUMPER ARM <i>x</i> <i>nn</i>	1.00	87.40		87.40 ✓
33	7	L52437-48020 COVER, FR BUMPER <i>x</i> <i>nn</i>	1.00	145.80		145.80 ✓
34	8	L52438-48020 COVER, FR BUMPER <i>x</i> <i>nn</i>	1.00	145.80		145.80 ✓
35	9	L52411-48030 GUARD, FR BUMPER <i>x</i> <i>nn</i>	1.00	173.80		173.80 ✓
36	0	L52114-48350 BRACKET, FR BUMPER <i>x</i> <i>nn</i>	1.00	173.80		173.80 ✓
37	1	L75392-35220 RETAINER, OUTSIDE <i>x</i> <i>nn</i>	2.00	4.30		8.60 ✓
38	2	T90467-07215 CLIP <i>x</i> <i>nn</i>	2.00	2.80		5.60 ✓
39	3	L89348-48010 RETAINER, ULTRASONIC <i>x</i> <i>nn</i>	2.00	20.90		41.80 ✓
40	4	L81210-48051 LAMP ASSY, FOG <i>x</i> <i>nn</i>	1.00	516.00		516.00 ✓
41	5	L81220-48051 LAMP ASSY, FOG, LH <i>x</i> <i>nn</i>	1.00	516.00		516.00 ✓
42	6	L81360-48130 LAMP ASSY, <i>x</i> <i>nn</i>	1.00	1199.90		1199.90 ✓
43	7	L81390-48090 LAMP ASSY, <i>x</i> <i>nn</i>	1.00	1199.90		1199.90 ✓

Steve CLKK
4/8/22, 1045a
00-11 AL
Exc - 7

P/P
By Bel H - 4 days

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				32,528.80
the Repairer of the following:		Please acknowledge receipt of vehicle	Parts 27,717.30	GST 7.00% 2,277.02
- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Part prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Labour 4,811.50	Less 0.00
			Sublet 0.00	
			Lubrication/Fluid 0.00	
			Others 0.00	Amount Due 34,805.82

Acknowledged by Repairer

Signature:

Date:

Customer Copy