



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z  
 Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896  
 HP: 98888885

## Estimation

Date: 4/8/2022  
 Vehicle: SNC4306K  
 Make / Model: TOYOTA ALTIS  
 Chassis No: ECICS

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET <i>bt</i>	1	\$ 1,354.00	\$ 1,354.00
2	BONNET LOCK <i>X sru</i>	1	\$ 312.00	\$ 312.00
3	BONNET RUBBER <i>X sru</i>	1	\$ 18.00	\$ 18.00
4	BONNET HINGES ? <i>X sru</i>	2	\$ 68.00	\$ 136.00
5	FRONT BUMPER <i>de</i>	1	\$ 798.00	\$ 798.00
6	FRONT BUMPER REINFORCEMENT <i>X sru</i>	1	\$ 398.00	\$ 398.00
7	FRONT BUMPER SPONGE <i>ca</i>	1	\$ 198.00	\$ 198.00
8	FRONT BUMPER SIDE RETAINER <i>X sru</i>	2	\$ 98.00	\$ 196.00
9	FRONT BUMPER CENTRE GRILLE <i>ca</i>	1	\$ 612.00	\$ 612.00
10	FRONT BUMPER FOGLAMP COVER <i>X sru</i>	2	\$ 68.00	\$ 136.00
11	FRONT GRILLE <i>sch</i>	1	\$ 590.00	\$ 590.00
12	FRONT GRILLE TOP RUBBER <i>X sru</i>	1	\$ 75.00	\$ 75.00
13	FRONT GRILLE TOP GARNISH <i>X sru</i>	1	\$ 198.00	\$ 198.00
14	FRONT GRILLE LOGO <i>sru</i>	1	\$ 187.00	\$ 187.00
15	AIR CLEANER AIR DUCT <i>X sru</i>	1	\$ 212.00	\$ 212.00
16	FRONT SUPPORT PANEL <i>repar</i>	1	\$ 825.00	\$ 825.00
17	<i>1588.72</i> HEADLAMP LED RH - <i>ca</i> <i>pc</i>	<i>2</i>	\$ 2,798.00	\$ 5,596.00
				\$ 11,841.00
				Less 25%
				\$ 2,960.25
				<b>Total</b>
				\$ 8,880.75

924.15  
 X  
 X  
 X  
 581.10  
 X  
 ✓  
 X  
 286  
 X  
 446  
 X  
 X  
 98  
 X  
 XR  
 1588.72  
 4121.97  
 258  
 3091.47

S/Nett items:				
1	FRONT BUMPER CLIPS SET <i>m</i>	1	\$ 50.00	\$ 50.00
2	FRONT NUMBER PLATE <i>st</i>	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER LOWER GRILLE CLIPS SET <i>m</i>	1	\$ 50.00	\$ 50.00
4	FRONT BUMPER LOWER COVER GARNISH CLIPS SET <i>X m</i>	1	\$ 50.00	\$ 50.00
5	FRONT GRILLE CLIPS <i>m</i>	1	\$ 50.00	\$ 50.00
				\$ 3,060.00
Labour to: Front				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
3	REMOVE AND REPAIR FRONT SUPPORT, RADIA CONDENSOR	1	\$ 300.00	\$ 300.00
4	RE FOCUS FRONT HEADLAMP	1	\$ 80.00	\$ 80.00
5	TO CHECK ELECTRICAL WIRING	1	\$ 100.00	\$ 100.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 50.00	\$ 50.00
				\$ 1,730.00
<b>Parts Replacement Amount</b>				\$ 11,940.75

30  
 35  
 30  
 X  
 30  
 125  
 500  
 500  
 60  
 30  
 30  
 30  
 1120