

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: INDIA	DATE	: 04/08/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLH3991K		
MODEL	: TOYOTA HARRIER 2.0 A		25K600080138
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
	DATE : 2-Aug-22		
	TIME : 19:00HRS		
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Repair</i>	1	\$ 1,855.30	\$ 1,855.30
2	TAILGATE EMBLEM 'HARRIER' <i>New</i>	1	\$ 82.00	\$ 82.00
3	TAILGATE WINDSCREEN MOULDING <i>New</i>	1	\$ 190.50	\$ 190.50
4	REAR BUMPER <i>Rehnd</i>	1	\$ 1,855.80	\$ 1,855.80 1381
5	REAR BUMPER LOWER LID <i>Cut</i>	1	\$ 420.50	\$ 420.50
6	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80
7	REAR BUMPER SPONGE <i>New</i>	1	\$ 230.50	\$ 230.50

TOTAL PRICE \$ 4,759.40

LESS 25% \$ 1,189.85

SUB TOTAL PRICE \$ 3,569.55

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
2	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 220

TOTAL \$ 240.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 600.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 600.00	400	
3	REMOVE AND REFIX TAILGATE MECHANISM	\$ 140.00	X	
4	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
5	REMOVE AND REFIX REAR WINDSCREEN	\$ 140.00	X	

TOTAL

\$1,580.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,809.55
 TOTAL LABOUR COST : \$ 1,580.00
 TOTAL REPAIR COST : \$ 5,389.55

650

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :
 PART BY PART / LUMP SUM :
 NO OF DAYS :

FAX :

total: 2282.62
 L/S: 1.8K.
 03Days.